



#1 IN THE #2 BUSINESS!

1810 Murray Road, McKinleyville, CA 95519

(707) 839-2270 / Fax: (707) 839-2112

License #1022884

E-mail: info@stevesseptic.com

Onsite Wastewater Treatment System Inspection Report

Ordered by Whom: Joel Geck-Moeller

Date/Time Scheduled: 3/29/22

Site Address: 12 Hawks Hill Rd.
Loleta, CA 95551

Send Copy to: _____

Billing Address: _____

Phone: 707-273-0528

Email: loletagm@gmail.com

A. General Information: (Obtain as much as possible when inspection ordered)

Was a Homeowner Questionnaire completed? Yes No

Additional Comment: _____

Inspector Signature: _____

1.) Age of wastewater treatment system: _____ years.
 Water softener Garbage disposal Whirlpool bath Cleaning service

In-Home Business: type _____

Flow Meter: _____

2.) Number of people occupying dwelling: Currently: _____ Anticipated: _____
If currently unoccupied, for how long has it been vacant? _____ Months

3.) Number of bedrooms in dwelling: _____

Design: _____ Listing: _____

4.) Has there ever been a backup in the house? Yes No

5.) List any known repairs made to the system: _____

6.) Has the system recently been inspected by others? Yes No

7.) Is there a service contract for system components? Yes No

Company: _____

8.) Date the treatment tank last pumped: _____ Never to my knowledge

At what frequency? _____ Company: _____

The above information is true to the best of my knowledge.

Joel Geck-Moeller
Owner

3/29/22
Date

B. System Type

1.) Components of Wastewater Treatment System (complete as necessary)

Pretreatment Unit 1: Concrete Septic tank [1800] [gallons]
Pump: Pump Tank 1: _____ gpm/tdh [_____] [gallons]

Pretreatment Unit 2: _____ [_____] [gallons]
Pump: Pump Tank 2: _____ gpm/tdh [_____] [gallons]

Soil Treatment Unit: Leach field [_____] [square feet]

Additional Components:

3.) Gray-water run-off or drainage system?

None Surface Subsurface Discharge

Comments:

C. Evaluation Procedures: (Check the appropriate boxes)

Locate, access and open the septic tank cover

Are tank lids at grade? If not, depth: Solid: 3" Liquid: 3" Round / Square Yes No

Is the cover secure? Yes No

Are access risers in place? Yes No

Can surface water infiltrate into the tank? Yes No

Indication of previous failure? Yes No

Inspect lid, inspect level, measure sludge and scum Yes No

Scum level at primary side / secondary side of tank: 0 / 0

Sludge level at primary side / secondary side of tank: 0 / 0

Estimate % of solids in tank: 0 % (Septic tank is recommended to be pumped at 20% solids)

Was tank authorized to be pumped during inspection? Yes No

Please Note: Our Company cannot complete a full inspection without pumping out the primary treatment tank.

Pumped out primary treatment tank? Yes No

Listen and observe for backflow into the tank from the outlet pipe

Comments: Tank was empty upon inspection Initial: DD

Caution: Do not pump treatment tank if there is evidence of a malfunction in any portion of the system.

Does tank have an effluent filter? Yes No

Was effluent filter cleaned? Yes No

Run an operation test Yes No

Gallons added in the test _____ gallons

Inspect the condition of the primary treatment tank Yes No

(i.e. cracks, infiltration, deterioration or damage)

Inspect the integrity of the inlet and outlet baffles Yes No

(i.e. deterioration or damage)

NEVER enter the septic tank unless proper confined space entry procedures are followed.

Does the system contain a dosing or pump tank, ejector or grinder pump?

Yes No

If so, did you check integrity of the tank (cracks, infiltration, etc?)

Yes No

Is the pump elevated off the bottom of the chamber?

Yes No

Does the pump work?

Yes No

Is there a check valve?

Yes No

Is there a purge hole?

Yes No

Is there a high water alarm?

Yes No

Does the alarm work?

Yes No

Do electrical connections appear satisfactory?

Yes No

Did you clean the pump tank?

Yes No

Is there a dosing meter reading?

Yes No

Probe the soil treatment area

Yes No

Seepage pit?

Yes No

Check for excessive moisture, odor and/or effluent

Type of Distribution:

Gravity

Pressure

Is There:

Indication of a previous failure?

Yes No

Seepage visible on the lawn?

Yes No

Lush vegetation present?

Yes No

Ponding water in the distribution media?

Yes No

Even distribution of effluent in the field?

Yes No

Determine approximate distance between water well and soil treatment area.

Approximate distance is _____ feet.

D. Sketch of System

For reproducible results, show dimensions from structures that will not change, such as corners or the house. Show details, such as the rod, in relation to the house to get the correct orientation. Show all located components.

See Attached.

E. Checklist Summary

- 1.) Pretreatment Unit 1 is in Excellent Satisfactory Poor condition.
 Pretreatment Unit 2 is in Excellent Satisfactory Poor condition.

Comments: Poor condition due to minor roots entering through the tank seams. Recommend removing roots and sealing. System has never been used, no inlet pipe.

- 2.) Soil Treatment area is in:

Rating:	Division of Environmental Health Standards
<input checked="" type="radio"/> Excellent Condition <i>Comments:</i>	<u>No noticeable rise in water level during filling.</u>
<input type="radio"/> Good Condition <i>Comments:</i>	Maximum water level rise of about 1-inch, with rapid decline to initial level within 5-minutes after end of filling.
<input type="radio"/> Satisfactory Condition <i>Comments:</i>	Maximum water level rise of about 2-inches, with decline to initial level within about 15-minutes after end of filling.
<input type="radio"/> Marginal Condition <i>Comments:</i>	Maximum water level rise of about 3-inches, with decline to initial water level within 30-minutes after end of filling.
<input type="radio"/> Poor Condition <i>Comments:</i>	Water level rise of more than 3-inches, with decline not reaching initial level within 30 minutes after end of filling.
<input type="radio"/> Failed <i>Comments:</i>	Water level rise of more than 3-inches, with no noticeable decline within 30-minutes after end of filling.

- 3.) Pump and pump tank are in Excellent Satisfactory Poor condition.

Comments: N/A




Rasmussen Rd

Hawks Hill Rd

Rasmussen Rd

Table Bluff Rd

Septic Tank



of Supervisors this 2nd day of November, 1943.

(SEAL) FRED J. MOORE, JR.

County Clerk and ex-officio Clerk of the Board of Supervisors of the County of Humboldt, State of California. By Ann Duffy, Deputy Clerk.

5838 Recorded at the request of County of Humboldt, November 2nd, 1943, at 25 minutes past 4 P.M., in book 263 of Deeds page 205, Records of the County of Humboldt.

W. J. Crane, Recorder.

No fee Compared: *W. J. Crane* By Crystal Gesler, Deputy.

DEED

We M. F. CLONEY and ELSIE E. CLONEY, his wife GRANT to CHRISTIAN S. RASMUSSEN and MARY RASMUSSEN, his wife, as joint tenants all that real property situated in the County of HUMBOLDT, State of California, bounded and described as follows, to-wit:

COMMENCING on the quarter section line at a point 1 rod north from the southwest corner of the southeast quarter of Section 6, Township 3 North, Range 1 West, Humboldt Meridian;

and running thence east parallel with the south line of said Section, 400 feet more or less to the county road leading from Table Bluff to the Light House;

thence northerly following said road 950 feet more or less to the west line of the southeast quarter of said Section;

and thence south on the quarter section line 800 feet more or less to the place of beginning.

WITNESS my hand this date: October 26 1943.

Elsie E. Cloney
M. F. Cloney



STATE OF CALIFORNIA, }
County of Humboldt. } SS.

On this date: November 2, 1943, before me the undersigned, a notary public in and for said county, personally appeared M. F. Cloney and Elsie E. Cloney, his wife known to me to be the persons whose names are subscribed to the within instrument, and acknowledged to me that they executed the same.

Witness my hand and official seal.

(SEAL) C. F. Edson
Notary Public in and for the County of Humboldt,
State of California.

5839 Recorded at the request of Belcher Abstract & Title Co., November 2nd 1943, at 30 minutes past 4 P.M., in book 263 of Deeds page 206, Records of the County of Humboldt.

W. J. Crane, Recorder.

Paid \$1.00 Compared: *W. J. Crane* By Crystal Gesler, Deputy.

BARGAIN AND SALE DEED

HELEN EBERSOLE, formerly HELEN HARRISON, FRED A ABRAHAMSON also known as FRED A ABREHAMSON, and HILMA FREEMAN McMAHON, formerly HILMA FREEMAN, the grantors, in consideration of TEN AND NO/100 dollars, the receipt whereof is hereby acknowledged, have sold, and BY THIS DEED do GRANT and CONVEY unto CLYDE E. SHULL, an unmarried man, the grantee, all that real