

COUNTY ADMINISTRATIVE OFFICE ADA Compliance Team COUNTY OF HUMBOLDT

825 5th Street, Suite 112, Eureka, CA 95501-1153 Telephone (844) 365-0352 Fax (707) 445-7299 ada@co.humboldt.ca.us

ADA Access Barrier Assessment Report

Humboldt County DHHS

605 K St. Eureka, CA 95501

Last Updated 12/16/2022

Leased


Barrier Count: 148

Open: 95

Closed: 45

Exceptions: 6

Safe Harbor: 2





Field Date:	11/14/2017 Repor	t Date: 1/9/2019 B	Barrier #: 1A		
Facility:	Humboldt County DHHS - 605 K St, Eureka				
Location:	Exterior - Walkway to Building				
Official Respon	sible: Property Own	er			
Consent Decre	e: No	Paragraph: M.51	Dwg: N/A		
Barrier Area:	Signage	Remediatio	n: Required		
Barrier Type:	ISA Directional Sign - R	oute			
Barrier Description:	No directional signage	provided where accessible	route diverges from mai	n route	
Code Referenc	es: CBC 11B-216.4.3 a	and 2010 ADAS 216.6 Advis	ory		
As Built Description:	No ISA sign indicating v	valkway as accessible entry	path to building		
Proposed Solution:	Provide compliant sign				
As-Built Meas:	1 Quantity:	EACH Cost Estimate: \$	250.00 BSR: 1 N	Necessary	
X Coordinate:	-124.160142	Y Coordinate: 40.801669	Z Coordinate	23.237165	
Implementatio	n: Priority 4	Phase	Date	Status Open	
Notes:					
Field Date:	11/14/2017 Repor	t Date: 1/9/2019 B	Sarrier #: 1B		
Facility:	Humboldt County DHH	S - 605 K St, Eureka			
Location:	Exterior - Walkway to E	Building			
Official Respon	sible: Property Own	er	6		
Consent Decre	e: No	Paragraph: M.51	Dwg: N/A	1	
Barrier Area:	Accessible Route - Exte	erior Remediatio	n: Required		
Barrier Type:	Clear Width - Accessibl	e Route			
Barrier Description:	Accessible route with r	no obstructions is not min.	48" wide, excluding the c	urb	
Code Referenc	es: CBC 11B-403.5.1 E	xception 3 and Caltrans Hig	ghway Design Manual 10	5.2	
As Built Description:	47-1/4" clear width				
Proposed Solution:	Demolish existing and	construct new accessible ro	oute		
As-Built Meas:	19 Quantity:	LF Cost Estimate: \$	2,375.00 BSR: 1 N	Necessary	
X Coordinate:	-124.160142	Y Coordinate: 40.801669	Z Coordinate	23.237165	
Implementatio	n: Priority 1	Phase	Date	Status Open	
Notes:					



Field Date:	11/14/2017 Report Date: 1/9/2019 Barrier #: 2A				
Facility:	Humboldt County DHHS - 605 K St, Eureka				
Location:	Exterior - Entrance Stairway				
Official Respo	nsible: Property Owner				
Consent Decre	ee: No Paragraph: M.51 Dwg: N/A				
Barrier Area:	Signage Remediation: Required				
Barrier Type:	ISA Directional Sign - No Access				
Barrier Description:	No directional signage provided at non-accessible route or entry				
Code Referen	CBC 11B-216.6 and 2010 ADAS 216.6				
As Built Description:	No ISA sign directing pedestrians to accessible entry walkway				
Proposed Solution:	Provide compliant directional signage				
As-Built Meas	Quantity: EACH Cost Estimate: \$250.00 BSR: 1 Necessary				
X Coordinate:	-124.160160 Y Coordinate: 40.801768 Z Coordinate: 23.237165				
Implementati	on: Priority 4 Phase Date Status Open				
Notes:					
Field Date:	11/14/2017 Report Date: 1/9/2019 Barrier #: 2B				
Facility:	Humboldt County DHHS - 605 K St, Eureka				
•	Trainbolat County Dillis 7005 K St, Eureka				
Location:	Exterior - Entrance Stairway				
-	Exterior - Entrance Stairway				
Location:	Exterior - Entrance Stairway nsible: Property Owner				
Location: Official Respo Consent Decre Barrier Area:	Exterior - Entrance Stairway nsible: Property Owner ee: No Paragraph: M.51 Dwg: N/A Stairways Remediation: Recommended				
Location: Official Respo Consent Decre Barrier Area:	Exterior - Entrance Stairway nsible: Property Owner ee: No Paragraph: M.51 Dwg: N/A				
Location: Official Respo Consent Decre Barrier Area:	Exterior - Entrance Stairway nsible: Property Owner ee: No Paragraph: M.51 Dwg: N/A Stairways Remediation: Recommended				
Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description:	Exterior - Entrance Stairway nsible: Property Owner ee: No Paragraph: M.51 Dwg: N/A Stairways Remediation: Recommended Handrail - Intermediate >88" wide				
Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description:	Exterior - Entrance Stairway nsible: Property Owner ee: No Paragraph: M.51 Dwg: N/A Stairways Remediation: Recommended Handrail - Intermediate >88" wide Stairway more than 88" in width lacks at least 1 intermediate handrail for each 88" of width				
Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built	Exterior - Entrance Stairway nsible: Property Owner ee: No Paragraph: M.51 Dwg: N/A Stairways Remediation: Recommended Handrail - Intermediate >88" wide Stairway more than 88" in width lacks at least 1 intermediate handrail for each 88" of width ces: Performance Standard				
Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Referent As Built Description: Proposed	Exterior - Entrance Stairway nsible: Property Owner ee: No Paragraph: M.51 Dwg: N/A Stairways Remediation: Recommended Handrail - Intermediate >88" wide Stairway more than 88" in width lacks at least 1 intermediate handrail for each 88" of width ces: Performance Standard No handrails provided at stairway wider than 88" Provide one intermediate handrail per 88" stairway clear width				
Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed Solution: As-Built Meas	Exterior - Entrance Stairway nsible: Property Owner ee: No Paragraph: M.51 Dwg: N/A Stairways Remediation: Recommended Handrail - Intermediate >88" wide Stairway more than 88" in width lacks at least 1 intermediate handrail for each 88" of width ces: Performance Standard No handrails provided at stairway wider than 88" Provide one intermediate handrail per 88" stairway clear width				
Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed Solution: As-Built Meas	Exterior - Entrance Stairway nsible: Property Owner ee: No Paragraph: M.51 Dwg: N/A Stairways Remediation: Recommended Handrail - Intermediate >88" wide Stairway more than 88" in width lacks at least 1 intermediate handrail for each 88" of width ces: Performance Standard No handrails provided at stairway wider than 88" Provide one intermediate handrail per 88" stairway clear width : 4 Quantity: LF Cost Estimate: \$900.00 BSR: 2 Recommended -124.160160 Y Coordinate: 40.801768 Z Coordinate: 23.237165				



Field Date:	11/14/2017 Repor	t Date: 1/9/2019 Barrier #: 2C			
Facility:	Humboldt County DHHS - 605 K St, Eureka				
Location:	Exterior - Entrance Sta	rway			
Official Respo	nsible: Property Own	er			
Consent Decre	ee: No	Paragraph: M.51 Dwg: N/A			
Barrier Area:	Stairways	Remediation: Required			
Barrier Type:	Handrail Extension - Pr	e-ADA 90° Turn			
Barrier Description:	Handrail extension doe stairway	es not extend beyond the stairway treads, in the same direction as the			
Code Referen	ces: CBC 11B-505.10 E	xception 3			
As Built Description:	Handrail extension tur	ns 90° to avoid protrusion into path of travel on one side			
Proposed Solution:	Replace handrails or re	design stairway to comply			
As-Built Meas	: 1 Quantity:	LF Cost Estimate: \$225.00 BSR: 4 Low Severity			
X Coordinate:	-124.160160	Y Coordinate: 40.801768 Z Coordinate: 23.237165			
Implementation	on: Priority 4	Phase Date Status Open			
Notes:					
Field Date:	11/14/2017 Repor	t Date: 1/9/2019 Barrier #: 2D			
Facility:	Humboldt County DHH	S - 605 K St, Eureka			
Location:	Exterior - Entrance Sta	irway			
Official Respo	nsible: Property Owr	ner			
Consent Decre	ee: No	Paragraph: M.51 Dwg: N/A			
Barrier Area:	Stairways	Remediation: Required			
Barrier Type:	Riser Height - Height in	Existing Area			
Barrier Description:	Stair riser height is not	between 4" and 7"			
Code Referen	ces: CBC 11B-504.2 an	d 2010 ADAS 504.2			
As Built Description:	7-1/2" stair riser heigh	t			
Proposed Solution:	Alter existing stairway	to comply			
As-Built Meas	: 40 Quantity:	SF Cost Estimate: \$10,000.00 BSR: 4 Low Severity			
X Coordinate:	-124.160160	Y Coordinate: 40.801768 Z Coordinate: 23.237165			
Implementation	on: Priority 4	Phase Date Status Open			
Notes:					



Field Date:	11/14/2017 Repo	rt Date: 1/9/2019 Barr	rier #: 3A	
Facility:	Humboldt County DHF	IS - 605 K St, Eureka		TO STATE OF THE ST
Location:	Exterior - Parking Lot			COUNT CASE ONLY
Official Respo	nsible: Property Owi	ner		* - C
Consent Decr	ee: No	Paragraph: M.51	Dwg: N/A	
Barrier Area:	Parking	Remediation:	Required	
Barrier Type:	Tow-Away Sign			
Barrier Description:	No tow-away sign prov	vided at lot entry or accessible	stalls	
Code Referen	ces: CBC 11B-502.8			
As Built Description:	No sign provided			
Proposed Solution:	Provide compliant sign	l		
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$250	0.00 BSR:	2 Recommended
X Coordinate:	-124.160107	Y Coordinate: 40.801500	Z Coordina	ate: 23.237165
Implementati	on: Priority 1	Phase Da	ate	Status Open
Notes:				
Field Date:	11/14/2017 Repo	rt Date: 1/9/2019 Barr	rier #: 3B	
Facility:	Humboldt County DHF	IS - 605 K St, Eureka	6	
Location:	Exterior - Parking Lot			3 (1
Official Respo	nsible: Property Owi	ner		
Consent Decr	ee: No	Paragraph: M.51	Dwg: N/A	
Barrier Area:	Parking	Remediation:	Required	
Barrier Type:	Accessible Stall Ratio -	26-50 total stalls		
Barrier Description:	Minimum of 2 accessil	ole stalls not provided in lot/st	ructure	
Code Referen	ces: CBC 11B-208.2 an	d 2010 ADAS 208.2		
As Built Description:	41 total stalls with 1 vastalls are required	an accessible stall and 1 standa	ard accessible stall	where min. 3 accessible
Proposed Solution:	Provide at least 2 acce	ssible stalls including 1 van acc	cessible stall	
As-Built Meas	: 0 Quantity:	EACH Cost Estimate: \$0.0		1 Necessary
X Coordinate:	-124.160107	Y Coordinate: 40.801500	Z Coordina	ate: 23.237165
Implementati				
Implementati	on: Priority 1	Phase Da	ate	Status Open



Field Date:	11/14/2017 Repo	rt Date: 1/9/2019	Barrier #: 4A	
Facility:	Humboldt County DHF	lS - 605 K St, Eureka		
Location:	Exterior - Parking Lot			
Official Respo	nsible: Property Owr	ner		181
Consent Decre	ee: No	Paragraph: M.51	Dwg: N/A	
Barrier Area:	Parking	Remediati	on: Required	
Barrier Type:	Accessible Stall Sign - L	ocation		
Barrier Description:	No reflectorized ISA sig	gn posted at front of stall		
Code Referen	ces: CBC 11B-502.6 an	d 2010 ADAS 502.6		
As Built Description:	Required sign not prov	vided at stall identified as v	an accessible	
Proposed Solution:	Provide required sign			
As-Built Meas	: 1 Quantity:	EACH Cost Estimate:	\$250.00 BSR: 1	L Necessary
X Coordinate:	-124.159789	Y Coordinate: 40.801540	Z Coordina	te: 23.237165
Implementati	on: Priority 1	Phase	Date	Status Open
Notes:				
Field Date:	11/14/2017 Repo	rt Date: 1/9/2019	Barrier #: 4B	
Facility:	Humboldt County DHF	IS - 605 K St, Eureka		
Location:	Exterior - Parking Lot			
Official Respo	nsible: Property Owr	ner		161
Consent Decre	ee: No	Paragraph: M.51	Dwg: N/A	
Barrier Area:	Parking	Remediati	on: Required	
Barrier Type:	Van Accessible Stall Sig	ţη		
Barrier Description:	No sign stating "Van A	ccessible" posted at front o	of stall	
Code Referen	ces: CBC 11B-502.6 an	d 2010 ADAS 502.6		
As Built Description:	No sign provided at sta	all identified as van accessi	ble	
Proposed Solution:	Provide compliant sign	n stating "van accessible"		
As-Built Meas	Quantity:	EACH Cost Estimate:	\$250.00 BSR: 2	2 Recommended
X Coordinate:	-124.159789	Y Coordinate: 40.801540	Z Coordina	te: 23.237165
Implementati	on: Priority 1	Phase	Date	Status Open
Notes:				



Field Date:	11/14/2017 Report	t Date: 1/9/2019 Ba	rrier #: 4C	
Facility:	Humboldt County DHH	S - 605 K St, Eureka		
Location:	Exterior - Parking Lot		,	
Official Respo	nsible: Property Own	er		131
Consent Decre	ee: No	Paragraph: M.51	Dwg: N/A	
Barrier Area:	Parking	Remediation	n: Required	
Barrier Type:	Accessible Stall Sign - Fi	ne Sign		
Barrier Description:	An additional sign or in	fo below the ISA does not st	tate "Minimum Fine \$25	0."
Code Referen	ces: CBC 11B-502.6.2			
As Built Description:	No fine sign provided a	t stall identified as van acces	ssible	
Proposed Solution:	Provide required sign			
As-Built Meas	Quantity:	EACH Cost Estimate: \$1	50.00 BSR: 3 H	indrance
X Coordinate:	-124.159789	Y Coordinate: 40.801540	Z Coordinate:	23.237165
Implementation	on: Priority 1	Phase	Date	Status Open
Notes:				
Field Date:	11/14/2017 Report	t Date: 1/9/2019 Ba	rrier #: 4D	
Facility:	Humboldt County DHH	S - 605 K St, Eureka		
Location:	Exterior - Parking Lot			
Official Respo				NO DIDVING
Consent Decre	ee: No	Paragraph: M.51	Dwg: N/A	NU PARKING
Barrier Area:	Parking	Remediation	n: Required	
Barrier Type:	Stall Slope - Existing (2.	1% to 3.0%)		
Barrier Description:	Accessible stall & aisle i	not max. 2.0% in all direction	ns (2.1% to 3.0%)	
Code Referen	ces: CBC 11B-502.4 and	d 2010 ADAS 502.4		
As Built Description:	Aisle 2.6% slope at stall	identified as van accessible		
Proposed Solution:	Regrade stall to make lo	evel and restripe		
As-Built Meas	Quantity:	EACH Cost Estimate: \$1	2,600.00 BSR: 4 L	ow Severity
X Coordinate:	-124.159789	Y Coordinate: 40.801540	Z Coordinate:	23.237165
Implementation	on: Priority 1	Phase	Date	Status Open
Notes:				



Field Date:	11/14/2017 Repo	rt Date: 1/9/2019 Barrier #:	4E		
Facility:	Humboldt County DHHS - 605 K St, Eureka				
Location:	Exterior - Parking Lot				
Official Respo	nsible: Property Owi	ner		13	
Consent Decre	ee: No	Paragraph: M.51 Dwg:	N/A		
Barrier Area:	Parking	Remediation: Requ	red		
Barrier Type:	Stall Dimensions - Veh	icle Space			
Barrier Description:	Accessible stall not mi	n. 9' x 18' or 14' x 18' including stand	ard access aisle		
Code Referen	ces: CBC 11B-502.2				
As Built Description:	16'-6" long at stall ider	ntified as van accessible			
Proposed Solution:	Restripe to provide co	mpliant stall and access aisle			
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$475.00	BSR: 2 Recom	mended	
X Coordinate:	-124.159789	Y Coordinate: 40.801540	Z Coordinate: 23.2	37165	
Implementati	on: Priority 1	Phase Date	Statu	Open	
Notes:					
Field Date:	11/14/2017 Repo	rt Date: 1/9/2019 Barrier #:	4F		
Facility:	Humboldt County DHF	IS - 605 K St, Eureka			
Location:	Exterior - Parking Lot				
Official Respo	nsible: Property Owi	ner	100	DADVING	
Consent Decre	ee: No	Paragraph: M.51 Dwg:	N/A	PARKING	
Barrier Area:	Parking	Remediation: Requ	red		
Barrier Type:	Stall Dimensions - Acco	ess Aisle			
Barrier Description:	Accessible access aisle	not min. 5' wide x 18' long (standard	accessible stall)		
Code Referen	ces: CBC 11B-502.3.1				
As Built Description:	16'-6" long at stall ider	ntified as van accessible			
Proposed Solution:	Restripe to provide co	mpliant stall and access aisle			
As-Built Meas	: 0 Quantity:	EACH Cost Estimate: \$0.00	BSR: 2 Recom	mended	
X Coordinate:	-124.159789	Y Coordinate: 40.801540	Z Coordinate: 23.2	37165	
Implementati	on: Priority 1	Phase Date	Statu	s Open	
Notes:			_		



Field Date:	11/14/2017 Report	t Date: 1/9/2019 Bar	rier #: 4G	
Facility:	Humboldt County DHH	S - 605 K St, Eureka		
Location:	Exterior - Parking Lot			
Official Respo	nsible: Property Own	er		
Consent Decre	ee: No	Paragraph: M.51	Dwg: N/A	WO PARKING
Barrier Area:	Parking	Remediation:	Required	
Barrier Type:	Accessible Stall Aisle - B	Border		
Barrier Description:	Access aisle lacks a blue	e border or cross-hatching ma	ax. 36" apart that contr	ast with stall surface
Code Referen	ces: CBC 11B-502.3.3			
As Built Description:	Bottom of access aisle i	not framed in blue		
Proposed Solution:	Provide required stripir	ng		
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$15	0.00 BSR: 3 H	indrance
X Coordinate:	-124.159789	Y Coordinate: 40.801540	Z Coordinate:	23.237165
Implementati	on: Priority 1	Phase D	ate	Status Open
Notes:				
Field Date:	11/14/2017 Report	t Date: 1/9/2019 Bar	rier #: 4H	
Facility:	Humboldt County DHH	S - 605 K St, Eureka	The state of the s	1
Location:	Exterior - Parking Lot		,	
Official Respo	nsible: Property Own	er		[See]
Consent Decre	ee: No	Paragraph: M.51	Dwg: N/A	18 X
Barrier Area:	Parking	Remediation:	Required	-
Barrier Type:	Location - Shortest Pos	sible Route		
Barrier Description:	Accessible stalls not loc	rated on shortest possible rou	ute to an accessible ent	rance
Code Referen	ces: CBC 11B-208.3.1 a	nd 2010 ADAS 208.3.1		
As Built Description:	Accessible stall not pro	vided on shortest possible ro	ute to each accessible	ouilding entry
Proposed Solution:	Relocate accessible stal	lls to location on shortest rou	ute to accessible entran	се
As-Built Meas	: 97 Quantity:	LF Cost Estimate: \$24	,250.00 BSR: 2 R	ecommended
X Coordinate:	-124.159789	Y Coordinate: 40.801540	Z Coordinate:	23.237165
Implementation	on: Priority 1	Phase D	ate	Status Open
Notes:				



Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 41
Facility: Humboldt County DHHS - 605 K St, Eureka
Location: Exterior - Parking Lot
Official Responsible: Property Owner
Consent Decree: No Paragraph: M.51 Dwg: N/A
Barrier Area: Parking Remediation: Required
Barrier Type: Accessible Stall - Location
Barrier Accessible stall location forces people to travel behind cars other than their own to reach building
Code References: CBC 11B-502.7.1
As Built Description: Stall location forces people using the stall to travel behind cars they do not own
Proposed Solution: Relocate accessible stalls to location on shortest route to accessible entrance
As-Built Meas: 0 Quantity: JOB Cost Estimate: \$0.00 BSR: 1 Necessary
X Coordinate: -124.159789 Y Coordinate: 40.801540 Z Coordinate: 23.237165
Implementation: Priority 1 Phase Date Status Open
Notes:
Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 5A
Facility: Humboldt County DHHS - 605 K St, Eureka
Location: Exterior - Parking Lot
Official Responsible: Property Owner
Consent Decree: No Paragraph: M.51 Dwg: N/A
Barrier Area: Parking Remediation: Required
Barrier Type: Accessible Stall Sign - Location
Barrier Description: No reflectorized ISA sign posted at front of stall
Code References: CBC 11B-502.6 and 2010 ADAS 502.6
As Built Required sign not provided at stall identified as accessible Description:
Proposed Provide required sign Solution:
As-Built Meas: 1 Quantity: EACH Cost Estimate: \$250.00 BSR: 1 Necessary
X Coordinate: -124.159729 Y Coordinate: 40.801545 Z Coordinate: 23.237165
Implementation: Priority 1 Phase Date Status Open



Field Date:	11/14/2017 Repor	rt Date: 1/9/2019 B	arrier #: 5B		
Facility:	Humboldt County DHHS - 605 K St, Eureka				
Location:	Exterior - Parking Lot				
Official Respo	nsible: Property Owr	ier		TED !	
Consent Decre	ee: No	Paragraph: M.51	Dwg: N/A	The state of the s	
Barrier Area:	Parking	Remediatio	n: Required		
Barrier Type:	Accessible Stall Sign - F	ine Sign			
Barrier Description:	An additional sign or ir	fo below the ISA does not s	state "Minimum Fine \$25	50."	
Code Referen	ces: CBC 11B-502.6.2				
As Built Description:	No fine sign provided a	nt stall identified as accessib	ole		
Proposed Solution:	Provide required sign				
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$	150.00 BSR: 3 I	Hindrance	
X Coordinate:	-124.159729	Y Coordinate: 40.801545	Z Coordinate	: 23.237165	
Implementation	on: Priority 1	Phase	Date	Status Open	
Notes:					
Field Date:	11/14/2017 Repor	t Date: 1/9/2019 B	arrier #: 5C		
Facility:	Humboldt County DHH	S - 605 K St, Eureka			
Location:	Exterior - Parking Lot				
Official Respo	nsible: Property Owr	ier		18	
Consent Decre	ee: No	Paragraph: M.51	Dwg: N/A		
Barrier Area:	Parking	Remediatio	n: Required		
Barrier Type:	Stall Slope - Existing (2	.1% to 3.0%)			
Barrier Description:	Accessible stall & aisle	not max. 2.0% in all direction	ons (2.1% to 3.0%)		
Code Referen	ces: CBC 11B-502.4 an	d 2010 ADAS 502.4			
As Built Description:	2.6% slope at stall ider	tified as accessible			
Proposed Solution:	Regrade stall to make	evel and restripe			
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$	12,600.00 BSR: 4 I	ow Severity	
X Coordinate:	-124.159729	Y Coordinate: 40.801545	Z Coordinate	: 23.237165	
Implementation	on: Priority 1	Phase	Date	Status Open	
Notes:					



Field Date:	11/14/2017 Repo	t Date: 1/9/2019 Barı	rier #: 5D	
Facility:	Humboldt County DHF	S - 605 K St, Eureka		
Location:	Exterior - Parking Lot			
Official Respo	nsible: Property Owr	ier		[5]
Consent Decre	ee: No	Paragraph: M.51	Dwg: N/A	and the same of th
Barrier Area:	Parking	Remediation:	Required	
Barrier Type:	Stall Dimensions - Veh	cle Space		
Barrier Description:	Accessible stall not mi	n. 9' x 18' or 14' x 18' including	g standard access aisle	
Code Referen	ces: CBC 11B-502.2			
As Built Description:	16'-6" long at stall ider	itified as accessible		
Proposed Solution:	Restripe to provide co	mpliant stall and access aisle		
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$47	5.00 BSR: 2 R	ecommended
X Coordinate:	-124.159729	Y Coordinate: 40.801545	Z Coordinate:	23.237165
Implementati	on: Priority 1	Phase Da	ate	Status Open
Notes:				
Field Date:	11/14/2017 Repo	t Date: 1/9/2019 Barr	rier #: 5E	
Facility:	Humboldt County DHF	S - 605 K St, Eureka		1
Location:	Exterior - Parking Lot		,	
Official Respo	nsible: Property Owr	ier		[con-]
Consent Decre	ee: No	Paragraph: M.51	Dwg: N/A	181
Barrier Area:	Parking	Remediation:	Required	
Barrier Type:	Location - Shortest Pos	sible Route		
Barrier Description:	Accessible stalls not lo	cated on shortest possible rou	ute to an accessible ent	rance
Code Referen	ces: CBC 11B-208.3.1 a	and 2010 ADAS 208.3.1		
As Built Description:	Accessible stall not pro	vided on shortest possible ro	ute to each accessible	ouilding entry
Proposed Solution:	Relocate accessible sta	lls to location on shortest rou	ite to bldg	
As-Built Meas	: 0 Quantity:	LF Cost Estimate: \$0.0	00 BSR: 2 R	ecommended
X Coordinate:	-124.159729	Y Coordinate: 40.801545	Z Coordinate:	23.237165
Implementati	on: Priority 1	Phase Da	ate	Status Open
Notes:				



Field Date:	11/14/2017 Repo	rt Date: 1/9/2019 Barrier #: 5F	1		
Facility:	Humboldt County DHHS - 605 K St, Eureka				
Location:	Exterior - Parking Lot				
Official Respo	nsible: Property Ow	ner	[SIII]		
Consent Decr	ee: No	Paragraph: M.51 Dwg: N/A	18		
Barrier Area:	Parking	Remediation: Required			
Barrier Type:	Accessible Stall - Locat	ion			
Barrier Description:	Accessible stall location	n forces people to travel behind cars other than t	heir own to reach		
Code Referen	ces: CBC 11B-502.7.1				
As Built Description:	Stall lacks accessible re	oute that provides safe connection to accessible ro	oute		
Proposed Solution:	Relocate accessible st	alls to location on shortest route to accessible ent	rance		
As-Built Meas	: 0 Quantity:	JOB Cost Estimate: \$0.00 BSR:	1 Necessary		
X Coordinate:	-124.159729	Y Coordinate: 40.801545 Z Coordina	te: 23.237165		
Implementati	on: Priority 1	Phase Date	Status Open		
Notes:					
Field Date:	11/14/2017 Repo	rt Date: 1/9/2019 Barrier #: 6A			
Facility:	Humboldt County DH	dS - 605 K St, Eureka			
Location:	Exterior - K St- E Sidew	/alk			
Official Respo	nsible: Property Ow	ner			
Consent Decr	ee: No	Paragraph: M.51 Dwg: N/A			
Barrier Area:	Sidewalks	Remediation: Required	100		
Barrier Type:	Turning Space - T-Shap	ped (Level)			
Barrier Description:	T-shaped turning spac	e identified with a change in level of more than 1:	48 (2.0%)		
Code Referen	ces: CBC 11B-304.2 ar	d 2010 ADAS 304.2			
As Built Description:	4.7% slope in landing	at change of direction on driveway			
Proposed Solution:	Alter floor or ground s	urface to comply			
As-Built Meas	: 25 Quantity:	SF Cost Estimate: \$3,125.00 BSR:	2 Recommended		
X Coordinate:	-124.160116	Y Coordinate: 40.801467 Z Coordina	te: 23.237165		
Implementati	on: Priority 1	Phase Date	Status Open		
Notes:					



Field Date:	11/14/2017 Repo	ort Date: 1/9/2019	Barrier #: 6B	
Facility:	Humboldt County DHHS - 605 K St, Eureka			
Location:	Exterior - K St- E Sidev			
Official Respo				
Consent Decre		Paragraph: M.51	Dwg: N/A	
Barrier Area:	Sidewalks	Remedia	tion: Required	M.
Barrier Type:	Driveway - Cross Slope	e (4.1% to 4.9%)		
Barrier Description:	Driveway cross slope	exceeds 2.0% (4.1% to 4.9	9%)	
Code Referen	ces: CBC 11B-403.3 ar	nd PROWAG 302.6		
As Built Description:	4.7% cross slope and 2	13.2% running slope at dr	iveway flares	
Proposed Solution:	Provide min. 48" wide	elevel walkway through d	riveway	
As-Built Meas	: 15 Quantity:	LF Cost Estimate:	\$1,875.00	BSR: 2 Recommended
X Coordinate:	-124.160116	Y Coordinate: 40.80146	Z Coo	ordinate: 23.237165
Implementati	on: Priority 1	Phase	Date	Status Open
Notes:				

Barrier Removed From This Report and is in the City of Eureka Public Right of Way Report



Field Date:	11/14/2017 Report Date: 1/9/2019 Barrier #: 8A
Facility:	Humboldt County DHHS - 605 K St, Eureka
Location:	Main Entrance
Official Respo	nsible: Karen Clower, ADA Coordinator
Consent Decre	ee: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area:	Signage Remediation: Required
Barrier Type:	Room ID Sign - No Tactile Information
Barrier Description:	Room ID sign provided for sighted people lacks tactile info for the visually impaired
Code Referen	CBC 11B-216.2 and 2010 ADAS 216.2
As Built Description:	No tactile information provided where visual sign exists
Proposed Solution:	Provide room ID sign with tactile information at wall at latch side of door
As-Built Meas	Quantity: EACH Cost Estimate: \$250.00 BSR: 1 Necessary
X Coordinate:	N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation	on: Priority 4 Phase Date Status Closed
Notes: Clo	sed 12-07-2021 ADA Compliance Team. Photo in closed barrier folder.
Field Date:	11/14/2017 Report Date: 1/9/2019 Barrier #: 8B
	605
Facility:	Humboldt County DHHS - 605 K St, Eureka
•	Humboldt County DHHS - 605 K St, Eureka Main Entrance
Location:	
Location:	Main Entrance nsible: Property Owner
Location: Official Respo Consent Decre Barrier Area:	Main Entrance nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Remediation: Required
Location: Official Respo Consent Decre Barrier Area:	Main Entrance nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1
Location: Official Respo Consent Decre Barrier Area:	Main Entrance nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Remediation: Required
Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description:	Main Entrance nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Remediation: Required Automatic Opening Device - High Control
Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description:	Main Entrance Insible: Property Owner Insible: No Paragraph: M.51 Dwg: 1 of 1 Insible: Property Owner
Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built	Main Entrance nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Remediation: Required Automatic Opening Device - High Control Centerline of one push plate not 30" to 44" above the ground or floor Ces: CBC 11B-404.2.9 Exception 2c
Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed	Main Entrance nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Remediation: Required Automatic Opening Device - High Control Centerline of one push plate not 30" to 44" above the ground or floor ces: CBC 11B-404.2.9 Exception 2c 51" OC where high push plate is the only actuator provided Replace control
Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed Solution:	Main Entrance nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Remediation: Required Automatic Opening Device - High Control Centerline of one push plate not 30" to 44" above the ground or floor ces: CBC 11B-404.2.9 Exception 2c 51" OC where high push plate is the only actuator provided Replace control : 1 Quantity: JOB Cost Estimate: \$2,750.00 BSR: 1 Necessary
Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed Solution: As-Built Meas	Main Entrance nsible: Property Owner nsible: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Automatic Opening Device - High Control Centerline of one push plate not 30" to 44" above the ground or floor ces: CBC 11B-404.2.9 Exception 2c 51" OC where high push plate is the only actuator provided Replace control Replace control 1 Quantity: JOB Cost Estimate: \$2,750.00 BSR: 1 Necessary N/A Y Coordinate: N/A Z Coordinate: N/A



Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 8C
Facility: Humboldt County DHHS - 605 K St, Eureka
Location: Main Entrance
Official Responsible: Property Owner
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Doors or Gates Remediation: Required
Barrier Type: Automatic Opening Device - Dimensions
Barrier Description: Each push plate not min. 4" in diameter or min. 4" by 4" square
Code References: CBC 11B-404.2.9 Exception 2c
As Built 2" x 2" sign with 1" ISA symbol Description:
Proposed Solution: Provide compliant push plate or full length bar actuator
As-Built Meas: 0 Quantity: JOB Cost Estimate: \$0.00 BSR: 1 Necessary
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 2 Phase Date Status Open
Notes:
Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 8D
Facility: Humboldt County DHHS - 605 K St, Eureka
Location: Main Entrance
Official Responsible: Property Owner
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Doors or Gates Remediation: Required
Barrier Type: Automatic Opening Device - Two Controls
Barrier Description: At each location where push plates are provided, two push plates are not provided
Code References: CBC 11B-404.2.9 Exception 2c
As Built Description: Lower push plate (door opening device actuator) not provided
Proposed Solution: Provide additional push plate or full length bar actuator
As-Built Meas: 2 Quantity: JOB Cost Estimate: \$5,500.00 BSR: 1 Necessary
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 2 Phase Date Status Open
Notes:



Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 8E
Facility: Humboldt County DHHS - 605 K St, Eureka
Location: Main Entrance
Official Responsible: Property Owner
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Doors or Gates Remediation: Required
Barrier Type: Automatic Opening Device - ANSI/BHMA
Barrier Description: No sign visible from both sides reading "AUTOMATIC DOOR"
Code References: CBC 11B-404.2.9 Exception 2d
As Built Description: No automatic door sign provided
Proposed Provide ANSI/BHMA sign Solution:
As-Built Meas: 1 Quantity: EACH Cost Estimate: \$250.00 BSR: 1 Necessary
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 2 Phase Date Status Open
Notes:
Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 8F
Facility: Humboldt County DHHS - 605 K St, Eureka
Location: Main Entrance
Official Responsible: Property Owner
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Doors or Gates Remediation: Required
Barrier Type: Threshold (replacement)
Barrier Door/Gate threshold height exceeds 1/2" with a bevel Description:
Code References: CBC 11B-404.2.5 and 2010 ADAS 404.2.5
As Built Description: 3/4" high threshold
Proposed Provide new door threshold Solution:
As-Built Meas: 1 Quantity: EACH Cost Estimate: \$275.00 BSR: 1 Necessary
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 2 Phase Date Status Open
Notes:



Field Date:	11/14/2017 Repo	rt Date: 1/9/2019	Barrier #: 8G	- aos
Facility:	Humboldt County DH	IS - 605 K St, Eureka		
Location:	Main Entrance			
Official Respo	nsible: Property Ow	ner		
Consent Decr	ee: No	Paragraph: M.51	Dwg: 1 of 1	
Barrier Area:	Signage	Remediat	tion: Required	
Barrier Type:	Tactile Exit Sign - Exit			
Barrier Description:	Ground floor doors th	at exit to exterior not pro	vided with signs stating "	EXIT"
Code Referen	ces: CBC 11B-216.4.1	& 11B-703 and 2010 ADA	S 216.4.1	
As Built Description:	No tactile sign provide	d where required		
Proposed Solution:	Provide compliant sign	n at exit side of door		
As-Built Meas	: 1 Quantity:	EACH Cost Estimate:	\$250.00 BSR: 1	Necessary
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordinat	e: N/A
Implementati	on: Priority 4	Phase	Date	Status Open
Notes:				
Field Date:	11/14/2017 Repo	rt Date: 1/9/2019	Barrier #: 9A	808
Facility:	Humboldt County DH	IS - 605 K St, Eureka		
Location:	Lobby 100A			
Official Respo	nsible: Property Ow	ner		
Consent Decr	ee: No	Paragraph: M.51	Dwg: 1 of 1	
Barrier Area:	Controls and Mechani	sms Remediat	tion: Required	
Barrier Type:	Electrical Switches - Si	de Reach High Unobstruct	ted	
Barrier Description:	Light switch control bo	ox not max. 48" high meas	sured to the top of the ou	tlet box
Code Referen	ces: CBC 11B-308.1.1,	11B-308.3.1 and 2010 AD	AS 308.3	
As Built Description:	57-3/8" high			
Proposed Solution:	Relocate switch box to	op edge to max. 48" high		
As-Built Meas	: 1 Quantity:	EACH Cost Estimate:	\$750.00 BSR: 3	Hindrance
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordinat	e: N/A
Implementati	on: Priority 2	Phase	Date	Status Open
Notes:				



Field Date:	11/14/2017 Report Date: 1/9/2019 Barrier #: 9B
Facility:	Humboldt County DHHS - 605 K St, Eureka
Location:	Lobby 100A
Official Respon	nsible: Karen Clower, ADA Coordinator
Consent Decre	ee: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area:	Clear Floor Space Remediation: Required
Barrier Type:	Clear Floor Space - Wheelchair Use (Stored Items)
Barrier Description:	Clear floor space of min. 30" by 48" not provided at element required to be accessible
Code Reference	ces: CBC 11B-305 and 2010 ADAS 305
As Built Description:	No wheelchair space provided in waiting area
Proposed Solution:	Rearrange furniture to provide wheelchair access, as needed
As-Built Meas:	1 Quantity: JOB Cost Estimate: \$0.00 BSR: 1 Necessary
X Coordinate:	N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation	on: Priority 2 Phase Date Status Closed
Notes: Clos	sed 12-07-2021 ADA Compliance Team. Photo in closed barrier folder.
Field Date:	11/14/2017 Report Date: 1/9/2019 Barrier #: 9C
Facility:	Humboldt County DHHS - 605 K St, Eureka
Location:	Lobby 100A
Official Respon	nsible: Property Owner
Official Respon	
Consent Decre	Static Static
Consent Decre Barrier Area:	ee: No Paragraph: M.51 Dwg: 1 of 1
Consent Decre Barrier Area:	Per No Paragraph: M.51 Dwg: 1 of 1 Counters and Tables Remediation: Required
Consent Decre Barrier Area: Barrier Type: Barrier Description:	Paragraph: M.51 Dwg: 1 of 1 Counters and Tables Remediation: Required Counter - Surface Height
Consent Decre Barrier Area: Barrier Type: Barrier Description:	Counters and Tables Remediation: Required Counter - Surface Height No section at least 3 feet long between 28" and 34" provided at existing counter
Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built	Paragraph: M.51 Counters and Tables Remediation: Required Counter - Surface Height No section at least 3 feet long between 28" and 34" provided at existing counter CBC 11B-902.3 & 11B-904.4 and 2010 ADAS 902.3 & 904.4 36" high Provide min. 3 ft long section of counter at max. 34" high
Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed	Paragraph: M.51 Dwg: 1 of 1 Counters and Tables Remediation: Required Counter - Surface Height No section at least 3 feet long between 28" and 34" provided at existing counter CBC 11B-902.3 & 11B-904.4 and 2010 ADAS 902.3 & 904.4 36" high Provide min. 3 ft long section of counter at max. 34" high
Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed Solution:	Counters and Tables Remediation: Required Counter - Surface Height No section at least 3 feet long between 28" and 34" provided at existing counter CBC 11B-902.3 & 11B-904.4 and 2010 ADAS 902.3 & 904.4 36" high Provide min. 3 ft long section of counter at max. 34" high Quantity: EACH Cost Estimate: \$875.00 BSR: 3 Hindrance
Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed Solution: As-Built Meas:	Counters and Tables Remediation: Required Counter - Surface Height No section at least 3 feet long between 28" and 34" provided at existing counter CBC 11B-902.3 & 11B-904.4 and 2010 ADAS 902.3 & 904.4 36" high Provide min. 3 ft long section of counter at max. 34" high 1 Quantity: EACH Cost Estimate: \$875.00 BSR: 3 Hindrance N/A Z Coordinate: N/A Z Coordinate: N/A



Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 9D	-
Facility: Humboldt County DHHS - 605 K St, Eureka	100
Location: Lobby 100A	
Official Responsible: Property Owner	
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1	
Barrier Area: Counters and Tables Remediation: Required	
Barrier Type: Counter - Protruding Object	
Barrier Counter or table in route of travel protrudes more than 4" above 27" high Description:	
Code References: CBC 11B-307 and 2010 ADAS 307	
As Built Counter protrudes 12" at 34-1/2" high Description:	
Proposed Solution: Provide cane-detectable warning that reaches below 27" high for the visually impaired	
As-Built Meas: 1 Quantity: EACH Cost Estimate: \$550.00 BSR: 1 Necessary	
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A	
Implementation: Priority 2 Phase Date Status Open	
Notes:	
Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 9E	-
Facility: Humboldt County DHHS - 605 K St, Eureka	100
Location: Lobby 100A	
Official Responsible: Karen Clower, ADA Coordinator	
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1	
Barrier Area: Accessible Route - Interior Remediation: Required	
Barrier Type: Protruding Object - Wall Mounted Object	
Barrier Wall mounted object protrudes more than 4" into accessible route between 27" and 80" high Description:	1
Code References: CBC 11B-307.2 and 2010 ADAS 307.2	
As Built Suggestion box protrudes 6-1/8" at 43-1/2" high Description:	
Proposed Remove object or provide detectable warning (wing walls) Solution:	
As-Built Meas: 1 Quantity: EACH Cost Estimate: \$550.00 BSR: 1 Necessary	
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A	
Implementation: Priority 2 Phase Date Status Closed	
Notes: Closed 3-15-2021 ADA Compliance Team. Photo in closed barrier folder.	



Field Date:	11/14/2017 Repor	t Date: 1/9/2019	Barrier #: 9	9
Facility:	Humboldt County DHH	S - 605 K St, Eureka		
Location:	Lobby 100A			
Official Respo	nsible: Karen Clower,	ADA Coordinator		
Consent Decr	ee: No	Paragraph: M.51	Dwg: 1	of 1
Barrier Area:	Controls and Mechanis	sms Remedia	ntion: N/A	
Barrier Type:	Operable Part - Side Re	each High (Safe Harbor)		
Barrier Description:	Operable part at max.	54" high		
Code Referen	ces: ADA Title II, Subpa	art D, § 35.150 Existing fa	acilities § 35.15	0(b)(2)(i)
As Built Description:	Suggestion box 48-1/4			
Proposed Solution:	No remediation require harbor	ed. Control or mechanis	m complied wit	h prior code and is granted safe
As-Built Meas	: 1 Quantity:	EACH Cost Estimate:	\$0.00	BSR: 3 Hindrance
X Coordinate:	N/A	Y Coordinate: N/A	7	Coordinate: N/A
Implementati	on: Priority 2	Phase	Date	Status Closed
Notes:				
Field Date:	11/14/2017 Repor	t Date: 1/9/2019	Barrier #: 9	G
Field Date: Facility:	11/14/2017 Repor	,	Barrier #: 9	G
		,	Barrier #: 9	G
Facility: Location:	Humboldt County DHH	S - 605 K St, Eureka	Barrier #: 9	G
Facility: Location:	Humboldt County DHH Lobby 100A nsible: Karen Clower,	S - 605 K St, Eureka	Barrier #: 9	
Facility: Location: Official Respo Consent Decr	Humboldt County DHH Lobby 100A nsible: Karen Clower,	S - 605 K St, Eureka ADA Coordinator Paragraph: M.51		
Facility: Location: Official Respo Consent Decr Barrier Area:	Humboldt County DHH Lobby 100A Insible: Karen Clower, ee: No	S - 605 K St, Eureka ADA Coordinator Paragraph: M.51 sms Remedia	Dwg: 1	
Facility: Location: Official Respo Consent Decr Barrier Area:	Humboldt County DHH Lobby 100A Insible: Karen Clower, ee: No Controls and Mechanis	S - 605 K St, Eureka ADA Coordinator Paragraph: M.51 sms Remedia ch High (Safe Harbor)	Dwg: 1	
Facility: Location: Official Respo Consent Decr Barrier Area: Barrier Type: Barrier Description:	Humboldt County DHH Lobby 100A Insible: Karen Clower, ee: No Controls and Mechanis Flyer Holder - Side Rea Flyer holder point of co	S - 605 K St, Eureka ADA Coordinator Paragraph: M.51 sms Remedia ch High (Safe Harbor)	Dwg: 1 o	of 1
Facility: Location: Official Respo Consent Decr Barrier Area: Barrier Type: Barrier Description:	Humboldt County DHH Lobby 100A Insible: Karen Clower, ee: No Controls and Mechanis Flyer Holder - Side Rea Flyer holder point of co	ADA Coordinator Paragraph: M.51 ms Remedia ch High (Safe Harbor) ontrol at max. 54" high	Dwg: 1 o	of 1
Facility: Location: Official Respo Consent Decr Barrier Area: Barrier Type: Barrier Description: Code Referen As Built	Humboldt County DHH Lobby 100A Insible: Karen Clower, ee: No Controls and Mechanis Flyer Holder - Side Rea Flyer holder point of co	ADA Coordinator Paragraph: M.51 sms Remedia ch High (Safe Harbor) ontrol at max. 54" high	Dwg: 1 on the street of the st	of 1
Facility: Location: Official Respo Consent Decr Barrier Area: Barrier Type: Barrier Description: Code Referen As Built Description: Proposed	Humboldt County DHH Lobby 100A Insible: Karen Clower, ee: No Controls and Mechanis Flyer Holder - Side Rea Flyer holder point of co ces: ADA Title II, Subpa 53-1/2" high No remediation require	ADA Coordinator Paragraph: M.51 sms Remedia ch High (Safe Harbor) ontrol at max. 54" high	Dwg: 1 of ation: N/A acilities § 35.15	of 1 O(b)(2)(i)
Facility: Location: Official Respo Consent Decr Barrier Area: Barrier Type: Barrier Description: Code Referen As Built Description: Proposed Solution:	Humboldt County DHH Lobby 100A Insible: Karen Clower, ee: No Controls and Mechanis Flyer Holder - Side Rea Flyer holder point of co ces: ADA Title II, Subpa 53-1/2" high No remediation require EE 1 Quantity:	ADA Coordinator Paragraph: M.51 sms Remedia ch High (Safe Harbor) ontrol at max. 54" high art D, § 35.150 Existing fa	Dwg: 1 of the prior of \$0.00	of 1 O(b)(2)(i) ode and is granted safe harbor
Facility: Location: Official Respo Consent Decr Barrier Area: Barrier Type: Barrier Description: Code Referen As Built Description: Proposed Solution: As-Built Meas	Humboldt County DHH Lobby 100A Insible: Karen Clower, ee: No Controls and Mechanis Flyer Holder - Side Rea Flyer holder point of co ces: ADA Title II, Subpa 53-1/2" high No remediation require :: 1 Quantity:	ADA Coordinator Paragraph: M.51 sms Remedia ch High (Safe Harbor) ontrol at max. 54" high art D, § 35.150 Existing fa	Dwg: 1 of the prior of \$0.00	of 1 O(b)(2)(i) ode and is granted safe harbor BSR: 3 Hindrance



Field Date:	11/14/2017 Repor	t Date: 1/9/2019	Barrier #: 9H	
Facility:	Humboldt County DHH	S - 605 K St, Eureka		
Location:	Lobby 100A			a linear
Official Respon	nsible: Karen Clower,	ADA Coordinator		
Consent Decre	ee: No	Paragraph: M.51	Dwg: 1 of 1	
Barrier Area:	Signage	Remediat	ion: Required	
Barrier Type:	Room ID Sign - No Tact	ile Information		
Barrier Description:	Room ID sign provided	for sighted people lacks t	actile info for the visua	ally impaired
Code Reference	ces: CBC 11B-216.2 an	d 2010 ADAS 216.2		
As Built Description:	No tactile information	provided where visual sig	n exists at two doors	
Proposed Solution:	Provide room ID sign w	vith tactile information at	wall at latch side of do	oor
As-Built Meas:	Quantity:	EACH Cost Estimate:	\$500.00 BSR:	1 Necessary
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordin	ate: N/A
Implementation	on: Proiority 4	Phase	Date	Status Closed
Notes: Clos	sed 12-07-2021 ADA Co	mpliance Team. Photo in	Closed barrier folder.	
Field Date:	11/14/2017 Repor	t Date: 1/9/2019	Barrier #: 91	
Facility:	Humboldt County DHH	S - 605 K St, Eureka		
Location:	Lobby 100A			
Official Respon	nsible: Karen Clower,	ADA Coordinator		
Consent Decre		Paragraph: M.51	Dwg: 1 of 1	
Barrier Area:	Accessible Route - Inte	rior Remediat	ion: Required	
Barrier Type:	Protruding Object - Wa	Ill Mounted Object		
Barrier Description:	Wall mounted object p	rotrudes more than 4" in	to accessible route bet	ween 27" and 80" high
Code Reference	ces: CBC 11B-307.2 an	d 2010 ADAS 307.2		
As Built Description:	Hand sanitizer dispens	er protrudes 4-3/8" at 44-	5/8" high	
Proposed Solution:	Relocate/remount disp	enser or provide detecta	ble warning	
As-Built Meas:	Quantity:	EACH Cost Estimate:	\$125.00 BSR:	2 Recommended
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordin	ate: N/A
Implementation	on: Priority 2	Phase	Date	Status Closed
Notes: Clos	ed 3-15-2021 ADA Com	pliance Team. Photo in cl	osed barrier folder.	



Field Date:	11/14/2017 Repor	t Date: 1/9/2019	Barrier #: 10A	
Facility:	Humboldt County DHH	S - 605 K St, Eureka	-	
Location:	Corridor 100B		i	
Official Respor	nsible: Karen Clower,	ADA Coordinator		
Consent Decre	ee: No	Paragraph: M.51	Dwg: 1 of 1	
Barrier Area:	Signage	Remediati	ion: Required	
Barrier Type:	Room ID Sign - No Tacti	ile Information		
Barrier Description:	Room ID sign provided	for sighted people lacks t	actile info for the visually	impaired
Code Reference	ces: CBC 11B-216.2 and	d 2010 ADAS 216.2		
As Built Description:	No tactile information រុ	provided where visual sign	n exists at rooms 103 and	113
Proposed Solution:	Provide room ID sign w	ith tactile information at	wall at latch side of door	
As-Built Meas:	2 Quantity:	EACH Cost Estimate:	\$500.00 BSR: 11	Necessary
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordinate	: N/A
Implementation	on: Priority 4	Phase	Date	Status Closed
Notes: Clo	osed 12-07-2021 ADA C	ompliance Team. Photo ii	n Closed barrier folder.	
Field Date:	11/14/2017 Repor	t Date: 1/9/2019	Barrier #: 10B	
Facility:	Humboldt County DHH	S - 605 K St, Eureka		
Location:	Corridor 100B			
Official Respor	nsible: Property Own	er		
Consent Decre	ee: No	Paragraph: M.51	Dwg: 1 of 1	
Barrier Area:	Counters and Tables	Remediati	ion: Required	
Barrier Type:	Counter - Protruding O	bject		
Barrier Description:	Counter or table in rou	te of travel protrudes mo	re than 4" above 27" high	
Code Reference	ces: CBC 11B-307 and 2	2010 ADAS 307		
As Built Description:	Counter protrudes 25-1	L/2" at 29-3/4" high		
Proposed Solution:	Provide cane-detectabl	e warning that reaches be	elow 27" high for the visua	ally impaired
As-Built Meas:	2 Quantity:	EACH Cost Estimate:	\$1,100.00 BSR: 11	Necessary
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordinate	: N/A
Implementation	on: Priority 2	Phase	Date	Status Open
Notes:				



Field Date:	11/14/2017 Report	Date: 1/9/2019 Barrier #: 10C	
Facility:	Humboldt County DHHS	- 605 K St, Eureka	
Location:	Corridor 100B		
Official Respo	nsible: Property Owne	er	
Consent Decre	ee: No P	Paragraph: M.51 Dwg: 1 of 1	
Barrier Area:	Alarms	Remediation: Required	
Barrier Type:	Horn/Strobe - Corridor		
Barrier Description:	No horn/strobes in corri	idor	
Code Referen	ces: CBC 11B-702.1 and	2010 ADAS 702.1	
As Built Description:	Device not provided		
Proposed Solution:	Provide strobes in comm	non use area	
As-Built Meas	: 2 Quantity: E	EACH Cost Estimate: \$11,000.00	SSR: 1 Necessary
X Coordinate:	N/A Y	Coordinate: N/A Z Coo	rdinate: N/A
Implementati	on: Priority 2	Phase Date	Status Exception
Notes: Exce	eption 1 in CBC 907.5.2.3	and CBC 11B-215.1.	
Field Date:	11/14/2017 Report	Date: 1/9/2019 Barrier #: 11A	No. Of the last of
Facility:	Humboldt County DHHS	- 605 K St, Eureka	
Location:	Office 111		ALTOSOMOZA
Official Respo	nsible: Karen Clower, A	ADA Coordinator	
Consent Decre	ee: No P	Paragraph: M.51 Dwg: 1 of 1	
Barrier Area:	Signage	Remediation: Required	
Barrier Type:	Room ID Sign - No Tactil	e Information	
Barrier Description:	Room ID sign provided fo	or sighted people lacks tactile info for the v	visually impaired
Code Referen	ces: CBC 11B-216.2 and	2010 ADAS 216.2	
As Built Description:	No tactile information p	rovided where visual sign exists	
Proposed Solution:	Provide room ID sign wit	th tactile information at wall at latch side o	f door
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$250.00	SSR: 1 Necessary
X Coordinate:	N/A Y	Coordinate: N/A Z Coo	rdinate: N/A
Implementati	on: Priority 4	Phase Date	Status Closed
Notes:	losed 12-07-2021 ADA Co	ompliance Team. Photo in Closed barrier fo	older.



Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 11B
Facility: Humboldt County DHHS - 605 K St, Eureka
Location: Office 111
Official Responsible: Property Owner
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Doors or Gates Remediation: Required
Barrier Type: Door Closer - Interior Automatic Device
Barrier Description: Door opening force exceeds 5 lbf
Code References: CBC 11B-404.2.9 and 2010 ADAS 404.2.9
As Built Description: 10 lbf at fire rated door
Proposed Solution: Provide automatic door opening device to comply with fire code requirements and access requirement
As-Built Meas: 1 Quantity: EACH Cost Estimate: \$5,000.00 BSR: 1 Necessary
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 2 Phase Date Status Open
Notes:
Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 11C
Facility: Humboldt County DHHS - 605 K St, Eureka
Location: Office 111
Official Responsible: Property Owner
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Doors or Gates Remediation: Required
Barrier Type: Door Closer - Interior Sweep
Barrier Description: Door closer lacks min. 5 second sweep period/back check
Code References: CBC 11B-404.2.8.1 and ADA/ABA 404.2.8.1
As Built 2 second sweep Description:
Proposed Solution: Provide automatic door opening device to comply with fire code requirements and access requirement
As-Built Meas: 0 Quantity: EACH Cost Estimate: \$0.00 BSR: 2 Recommended
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 2 Phase Date Status Open
Notes:



Field Date:	11/14/2017 Repo	rt Date: 1/9/2019	Barrier #: 11D	
Facility:	Humboldt County DH	IS - 605 K St, Eureka	TARIS OF THE PROPERTY OF THE P	
Location:	Office 111			
Official Respo	nsible: Karen Clower	, ADA Coordinator	1	
Consent Decr	ee: No	Paragraph: M.51	Dwg: 1 of 1	
Barrier Area:	Doors or Gates	Remediati	ion: Required	
Barrier Type:	Maneuvering Cl - Hing	e App/Pull 60"		
Barrier Description:	Door/Gate at pull side	lacks min. 60" perpendicu	llar to door	
Code Referen	ces: CBC Figure 11B-4	04.2.4.1 and 2010 ADAS 40	04.2.4.1	
As Built Description:	Desk blocks maneuver	ing clearance at pull side c	of door	
Proposed Solution:	Rearrange furniture to	provide required maneuvo	ering clearance	
As-Built Meas	: 0 Quantity:	EACH Cost Estimate:	\$0.00 BSR: 1 N	Necessary
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordinate:	N/A
Implementati	on: Priority 2	Phase	Date	Status Closed
Notes:	Closed 12-07-2021 ADA	Compliance Team. Photo	in Closed barrier folder.	
Field Date:	11/14/2017 Repo	rt Date: 1/9/2019	Barrier #: 11E	
Facility:	Humboldt County DHF	IS - 605 K St, Eureka		
Location:	Office 111			
Official Respo	nsible: Karen Clower	, ADA Coordinator		
Consent Decre	ee: No	Paragraph: M.51	Dwg: 1 of 1	
Barrier Area:	Clear Floor Space	Remediati	ion: Required	
Barrier Type:	Clear Floor Space - Wh	eelchair Use (Stored Item	s)	
Barrier Description:	Clear floor space of m	n. 30" by 48" not provided	d at element required to b	e accessible
Code Referen	ces: CBC 11B-305 and	2010 ADAS 305		
As Built Description:	No wheelchair space p	rovided		
Proposed Solution:	Rearrange furniture to	provide wheelchair access	s, as needed	
As-Built Meas	: 1 Quantity:	JOB Cost Estimate:	\$0.00 BSR: 1 N	lecessary
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordinate	N/A
Implementati	on: Priority 2	Phase	Date	Status Closed
Notes:	Closed 12-07-2021 ADA	Compliance Team. Photo	in Closed barrier folder.	



Field Date:	11/14/2017 Repo	rt Date: 1/9/2019 Barrier #: 11F	
Facility:	Humboldt County DH	dS - 605 K St, Eureka	
Location:	Office 111		
Official Respo	nsible: Property Ow	ner	
Consent Decr	ee: No	Paragraph: M.51 Dwg: 1 of 1	11/1/
Barrier Area:	Alarms	Remediation: Required	
Barrier Type:	Horn/Strobe - Staff Ar	ea	
Barrier Description:	No horn/strobe in staf	f areas	
Code Referen	ces: CBC 11B-702.1 ar	d 2010 ADAS 702.1	
As Built Description:	Device not provided		
Proposed Solution:	Provide horn/strobe in	area where programs, services and activities take pl	ace
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$5,500.00 BSR: 3 H	lindrance
X Coordinate:	N/A	Y Coordinate: N/A Z Coordinate:	N/A
Implementati	on: Priority 2	Phase Date	Status Exception
Notes: Exce	eption 1 in CBC 907.5.2.	3 and CBC 11B-215.1.	
Field Date:	11/14/2017 Repo	rt Date: 1/9/2019 Barrier #: 12A	Question Pro-
Facility:	Humboldt County DH	dS - 605 K St, Eureka	
Location:	Office 112		
Official Respo	nsible: Karen Clower	, ADA Coordinator	
Consent Decr	ee: No	Paragraph: M.51 Dwg: 1 of 1	
Barrier Area:	Signage	Remediation: Required	
Barrier Type:	Room ID Sign - No Tac	tile Information	
Barrier Description:	Room ID sign provided	for sighted people lacks tactile info for the visually i	mpaired
Code Referen	ces: CBC 11B-216.2 ar	d 2010 ADAS 216.2	
As Built Description:	No tactile information	provided where visual sign exists	
Proposed Solution:	Provide room ID sign v	vith tactile information at wall at latch side of door	
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$250.00 BSR: 1 N	lecessary
X Coordinate:	N/A	Y Coordinate: N/A Z Coordinate:	N/A
Implementati	on: Priority 4	Phase Date	Status Closed
Notes: Clo	sed 12-07-2021 ADA Co	ompliance Team. Photo in Closed barrier folder.	



Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 12B
Facility: Humboldt County DHHS - 605 K St, Eureka
Location: Office 112
Official Responsible: Property Owner
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Doors or Gates Remediation: Required
Barrier Type: Door Closer - Interior Automatic Device
Barrier Door opening force exceeds 5 lbf Description:
Code References: CBC 11B-404.2.9 and 2010 ADAS 404.2.9
As Built 10 lbf at fire rated door Description:
Proposed Solution: Provide automatic door opening device to comply with fire code requirements and access requirement
As-Built Meas: 1 Quantity: EACH Cost Estimate: \$5,000.00 BSR: 1 Necessary
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 2 Phase Date Status Open
Notes:
Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 12C
Facility: Humboldt County DHHS - 605 K St, Eureka
Location: Office 112
Official Responsible: Property Owner
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Doors or Gates Remediation: Required
Barrier Type: Door Closer - Interior Sweep
Barrier Description: Door closer lacks min. 5 second sweep period/back check
Code References: CBC 11B-404.2.8.1 and ADA/ABA 404.2.8.1
As Built 1 second sweep Description:
Proposed Solution: Provide automatic door opening device to comply with fire code requirements and access requirement
As-Built Meas: 0 Quantity: EACH Cost Estimate: \$0.00 BSR: 2 Recommended
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 2 Phase Date Status Open
Notes:



Field Date:	11/14/2017 Repo	rt Date: 1/9/2019	Barrier #: 12D	
Facility:	Humboldt County DHF	IS - 605 K St, Eureka		
Location:	Office 112			=======================================
Official Respo	nsible: Karen Clower	, ADA Coordinator		
Consent Decre	ee: No	Paragraph: M.51	Dwg: 1 of 1	
Barrier Area:	Doors or Gates	Remediati	ion: Required	
Barrier Type:	Maneuvering Cl - Store	ed Items		
Barrier Description:	Door/Gate lacks requi	red maneuvering clearance	е	
Code Referen	ces: CBC Figure 11B-40	04.2.4.1 and 2010 ADAS 40	04.2.4.1	
As Built Description:	Desk blocks maneuver	ing clearance at pull side c	of door	
Proposed Solution:	Rearrange furniture to	provide required maneuve	ering clearance	
As-Built Meas	: 1 Quantity:	EACH Cost Estimate:	\$125.00 BS	R: 1 Necessary
X Coordinate:	N/A	Y Coordinate: N/A	Z Coord	dinate: N/A
Implementati	on: Priority 2	Phase	Date	Status Closed
Notes: Clo	sed 12-07-2021 ADA C	ompliance Team. Photo in	Closed barrier folde	er.
Field Date:	11/14/2017 Repo	rt Date: 1/9/2019	Barrier #: 12E	
Facility:	Humboldt County DHF	IS - 605 K St, Eureka		
Location:	Office 112			
Official Respo	nsible: Karen Clower	, ADA Coordinator		
Consent Decre	ee: No	Paragraph: M.51	Dwg: 1 of 1	
Barrier Area:	Clear Floor Space	Remediati	on: Required	
Barrier Type:	Clear Floor Space - Wh	eelchair Use (Stored Items	s)	
Barrier Description:	Clear floor space of mi	n. 30" by 48" not provided	d at element require	d to be accessible
Code Referen	ces: CBC 11B-305 and	2010 ADAS 305		
As Built Description:	No wheelchair space p	rovided		
Proposed Solution:	Rearrange furniture to	provide wheelchair access	s, as needed	
As-Built Meas	: 1 Quantity:	JOB Cost Estimate:	\$0.00 BS	R: 1 Necessary
X Coordinate:	N/A	Y Coordinate: N/A	Z Coord	dinate: N/A
Implementati	on: Priority 2	Phase	Date	Status Closed
Notes: Clos	ed 3-15-2021 ADA Com	pliance Team. Photo in clo	osed barrier folder.	



Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 12F
Facility: Humboldt County DHHS - 605 K St, Eureka
Location: Office 112
Official Responsible: Property Owner
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Alarms Remediation: Required
Barrier Type: Horn/Strobe - Staff Area
Barrier No horn/strobe in staff areas Description:
Code References: CBC 11B-702.1 and 2010 ADAS 702.1
As Built Device not provided Description:
Proposed Provide horn/strobe in area where programs, services and activities take place Solution:
As-Built Meas: 1 Quantity: EACH Cost Estimate: \$5,500.00 BSR: 3 Hindrance
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 2 Phase Date Status Exception
Notes: Exception 1 in CBC 907.5.2.3 and CBC 11B-215.1.
Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 13A
Facility: Humboldt County DHHS - 605 K St, Eureka
Location: Conference Room 104
Official Responsible: Karen Clower, ADA Coordinator
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Signage Remediation: Required
Barrier Type: Room ID Sign - No Tactile Information
Barrier Room ID sign provided for sighted people lacks tactile info for the visually impaired Description:
Code References: CBC 11B-216.2 and 2010 ADAS 216.2
As Built No tactile information provided where visual sign exists Description:
Proposed Provide room ID sign with tactile information at wall at latch side of door Solution:
As-Built Meas: 1 Quantity: EACH Cost Estimate: \$250.00 BSR: 1 Necessary
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 4 Phase Date Status Closed
Notes: Closed 12-07-2021 ADA Compliance Team. Photo in closed barrier folder.



Field Date:	11/14/2017 Repo	rt Date: 1/9/2019 B	Barrier #: 13B	
Facility:	Humboldt County DH	IS - 605 K St, Eureka		
Location:	Conference Room 104		the state of the s	
Official Respo	nsible: Property Own	ner		
Consent Decr	ee: No	Paragraph: M.51	Dwg: 1 of 1	
Barrier Area:	Doors or Gates	Remediatio	on: Required	
Barrier Type:	Door Closer - Interior	Automatic Device		
Barrier Description:	Door opening force ex	ceeds 5 lbf		
Code Referen	ces: CBC 11B-404.2.9	and 2010 ADAS 404.2.9		
As Built Description:	10 lbf at fire rated doc	r		
Proposed Solution:	Provide automatic dod requirement	or opening device to comply	y with fire code requirem	ents and access
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$	55,000.00 BSR: 1 N	lecessary
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordinate:	N/A
Implementati	on: Priority 2	Phase	Date	Status Open
Notes:				
Field Date:	11/14/2017 Repo	rt Date: 1/9/2019 B	Barrier #: 13C	
Facility:	Humboldt County DH	IS - 605 K St, Eureka		
Location:	Conference Room 104		- See	
Official Respo	nsible: Property Owi	ner		
Consent Decr	ee: No	Paragraph: M.51	Dwg: 1 of 1	All lines
Barrier Area:	Doors or Gates	Remediatio	on: Required	
Barrier Type:	Door Closer - Interior S	Sweep		
Barrier Description:	Door closer lacks min.	5 second sweep period/ba	ck check	
Code Referen	ces: CBC 11B-404.2.8.	1 and ADA/ABA 404.2.8.1		
As Built Description:	3 second sweep			
Proposed Solution:	Provide automatic dod requirement	or opening device to comply	y with fire code requirem	ents and access
As-Built Meas	: 0 Quantity:	EACH Cost Estimate: \$	0.00 BSR: 2 R	Recommended
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordinate:	
Implementati	on: Priority 2	Phase	Date	Status Open
Notes:				



Field Date:	11/14/2017 Repo	rt Date: 1/9/2019 B	Barrier #: 13D	
Facility:	Humboldt County DHF	IS - 605 K St, Eureka		9
Location:	Conference Room 104			100
Official Respor	nsible: Karen Clower	, ADA Coordinator		
Consent Decre	ee: No	Paragraph: M.51	Dwg: 1 of 1	
Barrier Area:	Doors or Gates	Remediatio	on: Required	
Barrier Type:	Maneuvering Cl - Store	ed Items		
Barrier Description:	Door/Gate lacks requi	red maneuvering clearance		
Code Referenc	ces: CBC Figure 11B-40	04.2.4.1 and 2010 ADAS 404	4.2.4.1	
As Built Description:	Table blocks maneuve	ring clearance at pull side o	of door	
Proposed Solution:	Rearrange furniture to	provide required maneuve	ring clearance	
As-Built Meas:	1 Quantity:	EACH Cost Estimate: \$	BSR: 1 N	lecessary
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordinate:	N/A
Implementation	on: Priority 2	Phase	Date	Status Closed
Notes:	Clo	sed 12-07-2021 ADA Compl	liance Team. Photo in clo	sed barrier folder.
Field Date:	11/14/2017 Repo	rt Date: 1/9/2019 B	Barrier #: 13E	5
Facility:	Humboldt County DHF	IS - 605 K St, Eureka	1	
Location:	Conference Room 104			
Official Respor	nsible: Karen Clower	, ADA Coordinator		
Consent Decre	ee: No	Paragraph: M.51	Dwg: 1 of 1	
Barrier Area:	Accessible Route - Inte	erior Remediation	on: Required	
Barrier Type:	Clear Width - 36" Wide	e (Stored Items)		
Barrier Description:	Accessible route clear	width is not min. 36" wide		
Code Referenc	ces: CBC 11B-403.5.1	and 2010 ADAS 403.5.1		
As Built Description:	Furniture or stored ite	ms block circulation route a	and prevent passage thro	ugh space
Proposed Solution:	Rearrange furniture to	provide min. 36" wide pas	sage space through room	
As-Built Meas:		JOB Cost Estimate: \$	BSR 2 P	
,	1 Quantity:	JOB Cost Estimate: 13	50.00 B5K: 2 K	ecommended
X Coordinate:		Y Coordinate: N/A	Z Coordinate:	
	N/A			



Field Date:	11/14/2017 Repo	rt Date: 1/9/2019	Barrier #: 13F	
Facility:	Humboldt County DHF	IS - 605 K St, Eureka		
Location:	Conference Room 104			
Official Respon	sible: Karen Clower,	ADA Coordinator		
Consent Decre	e: No	Paragraph: M.51	Dwg: 1 of 1	A COL
Barrier Area:	Controls and Mechanis	sms Remedia	tion: Required	
Barrier Type:	Operable Part - Clear F	loor Space (Stored Items)	
Barrier Description:	Clear floor space for po	erson using wheelchair no	ot provided at operable	e part
Code Referenc	es: CBC 11B-305.3 an	d 2010 ADAS 305.3		
As Built Description:	Coat stand clear floor s	space not accessible		
Proposed Solution:	Provide additional hoo	k in accessible location		
As-Built Meas:	1 Quantity:	EACH Cost Estimate:	\$125.00 BSR:	2 Recommended
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordir	nate: N/A
Implementatio	n: Priority 2	Phase	Date	Status Closed
Notes: Close	ed 12-07-2021 ADA Co	mpliance Team. Photo ir	closed barrier folder.	
Field Date:	11/14/2017 Repo	rt Date: 1/9/2019	Barrier #: 13G	
Facility:	Humboldt County DHF	IS - 605 K St, Eureka		
Location:	Conference Room 104			
Official Respon	sible: Karen Clower	, ADA Coordinator		
Consent Decre	e: No	Paragraph: M.51	Dwg: 1 of 1	100
Barrier Area:	Controls and Mechanis	sms Remedia	tion: Required	
Barrier Type:	Clothing Hook or Rod -	Height		
Barrier Description:	Clothing hooks not ma	x. 48" high AFF		
Code Referenc	es: CBC 11B-308.2.1 a	and 2010 ADAS 308.2.1		
As Built Description:	Coat hook above 48" h	igh		
Proposed Solution:	Provide additional hoo	k in accessible location		
As-Built Meas:	1 Quantity:	EACH Cost Estimate:	\$125.00 BSR:	2 Recommended
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordir	nate: N/A
Implementatio	n: Priority 2	Phase	Date	Status Closed
Notes: Clos	sed 12-07-2021 ADA Co	ompliance Team. Photo i	n closed barrier folder.	



Field Date:	11/14/2017 Repo	rt Date: 1/9/2019 Barrier #: 13H	
Facility:	Humboldt County DHF	IS - 605 K St, Eureka	Yax
Location:	Conference Room 104		
Official Respo	nsible: Property Owr	ner	
Consent Decre	ee: No	Paragraph: M.51 Dwg: 1 of 1	
Barrier Area:	Alarms	Remediation: Required	
Barrier Type:	Horn/Strobe - Meeting	g Room	
Barrier Description:	No horn/strobes in me	eeting room	
Code Referen	ces: CBC 11B-702.1 an	d 2010 ADAS 702.1	
As Built Description:	Device not provided		
Proposed Solution:	Provide strobes in com	nmon use area	
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$5,500.00 BSR:	1 Necessary
X Coordinate:	N/A	Y Coordinate: N/A Z Coordina	te: N/A
Implementation	on: Priority 2	Phase Date	Status Exception
Notes: Exce	eption 1 in CBC 907.5.2	.3 and CBC 11B-215.1.	
Field Date:	11/14/2017 Repo	rt Date: 1/9/2019 Barrier #: 14A	
Facility:	Humboldt County DHF	IS - 605 K St, Eureka	0 0
Location:	Corridor 100C		
Official Respo	nsible: Karen Clower	, ADA Coordinator	
Consent Decre	ee: No	Paragraph: M.51 Dwg: 1 of 1	
Barrier Area:	Signage	Remediation: Required	
Barrier Type:	Room ID Sign - No Tact	tile Information	
Barrier			
Description:	Room ID sign provided	for sighted people lacks tactile info for the visual	ly impaired
	Room ID sign provided		ly impaired
	ces: CBC 11B-216.2 an		ly impaired
Code Referend	ces: CBC 11B-216.2 an	d 2010 ADAS 216.2	
Code Reference As Built Description: Proposed	Ces: CBC 11B-216.2 an No tactile information Provide room ID sign v	d 2010 ADAS 216.2 provided where visual sign exists at room 102 with tactile information at wall at latch side of doo	
Code Reference As Built Description: Proposed Solution:	Ces: CBC 11B-216.2 and No tactile information Provide room ID sign volume in Quantity:	d 2010 ADAS 216.2 provided where visual sign exists at room 102 with tactile information at wall at latch side of doo	r 1 Necessary
Code Reference As Built Description: Proposed Solution: As-Built Meas	No tactile information Provide room ID sign v 1 Quantity:	d 2010 ADAS 216.2 provided where visual sign exists at room 102 with tactile information at wall at latch side of doo EACH Cost Estimate: \$250.00 BSR: 2	r 1 Necessary



Field Date:	11/14/2017 Report Date: 1/9/2019 Barrier #: 14B
Facility:	Humboldt County DHHS - 605 K St, Eureka
Location:	Corridor 100C
Official Respo	nsible: Property Owner
Consent Decre	ee: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area:	Controls and Mechanisms Remediation: N/A
Barrier Type:	Electrical Switches - Side Reach High (Safe Harbor)
Barrier Description:	Light switch control box top edge at max. 54" high measured to top of box
Code Referen	ces: ADA Title II, Subpart D, § 35.150 Existing facilities § 35.150(b)(2)(i)
As Built Description:	52-1/8" high
Proposed Solution:	No remediation required. Control or mechanism complied with prior code and is granted safe harbor
As-Built Meas	: 1 Quantity: EACH Cost Estimate: \$0.00 BSR: 4 Low Severity
X Coordinate:	N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation	on: Priority 2 Phase Date Status Safe Harbor
Notes:	
Field Date:	11/14/2017 Report Date: 1/9/2019 Barrier #: 14C
Facility:	Humboldt County DHHS - 605 K St, Eureka
Location:	Corridor 100C
Official Respo	nsible: Property Owner
Consent Decre	
	ee: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area:	Signage Remediation: Required
	Signage Remediation: Required
Barrier Type: Barrier Description:	Signage Remediation: Required Tactile Exit Sign - Exit
Barrier Type: Barrier Description:	Signage Remediation: Required Tactile Exit Sign - Exit Ground floor doors that exit to exterior not provided with signs stating "EXIT"
Barrier Type: Barrier Description: Code Reference As Built	Signage Remediation: Required Tactile Exit Sign - Exit Ground floor doors that exit to exterior not provided with signs stating "EXIT" Ces: CBC 11B-216.4.1 & 11B-703 and 2010 ADAS 216.4.1
Barrier Type: Barrier Description: Code Reference As Built Description: Proposed	Signage Remediation: Required Tactile Exit Sign - Exit Ground floor doors that exit to exterior not provided with signs stating "EXIT" ces: CBC 11B-216.4.1 & 11B-703 and 2010 ADAS 216.4.1 No tactile sign provided where required Provide compliant sign at exit side of door
Barrier Type: Barrier Description: Code Reference As Built Description: Proposed Solution:	Signage Remediation: Required Tactile Exit Sign - Exit Ground floor doors that exit to exterior not provided with signs stating "EXIT" ces: CBC 11B-216.4.1 & 11B-703 and 2010 ADAS 216.4.1 No tactile sign provided where required Provide compliant sign at exit side of door 1 Quantity: EACH Cost Estimate: \$250.00 BSR: 1 Necessary
Barrier Type: Barrier Description: Code Reference As Built Description: Proposed Solution: As-Built Meas	Signage Remediation: Required Tactile Exit Sign - Exit Ground floor doors that exit to exterior not provided with signs stating "EXIT" ces: CBC 11B-216.4.1 & 11B-703 and 2010 ADAS 216.4.1 No tactile sign provided where required Provide compliant sign at exit side of door : 1 Quantity: EACH Cost Estimate: \$250.00 BSR: 1 Necessary N/A Y Coordinate: N/A Z Coordinate: N/A



Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 14D
Facility: Humboldt County DHHS - 605 K St, Eureka
Location: Corridor 100C
Official Responsible: Property Owner
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Doors or Gates Remediation: Required
Barrier Type: Door Closer - Exterior Adjustment
Barrier Door opening force exceeds 5 lbf Description:
Code References: CBC 11B-404.2.9
As Built 10 lbf Description:
Proposed Replace or adjust existing closer Solution:
As-Built Meas: 1 Quantity: EACH Cost Estimate: \$450.00 BSR: 1 Necessary
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 2 Phase Date Status Open
Notes:
Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 14E
Facility: Humboldt County DHHS - 605 K St, Eureka
Location: Corridor 100C
Official Responsible: Property Owner
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Doors or Gates Remediation: Required
Barrier Type: Door Closer - Exterior Sweep
Barrier Description: Door closer lacks min. 5 second sweep period/back check
Code References: CBC 11B-404.2.8.1 and 2010 ADAS 404.2.8.1
As Built 3 second sweep Description:
Proposed Solution: Replace or adjust existing closer
As-Built Meas: 0 Quantity: EACH Cost Estimate: \$0.00 BSR: 2 Recommended
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 2 Phase Date Status Open
Notes:



Field Date:	11/14/2017 Repo	rt Date: 1/9/2019 Barrier #: 14F			
Facility:	Humboldt County DHF	IS - 605 K St, Eureka			
Location:	Corridor 100C				
Official Respo	nsible: Property Own	ner			
Consent Decr	ee: No	Paragraph: M.51 Dwg: 1 of 1			
Barrier Area:	Signage	Remediation: Required			
Barrier Type:	ISA Directional Sign - N	Ion-accessible Entrance			
Barrier Description:	No ISA directional sign	posted indicating location/route to accessib	ole entry		
Code Referen	ces: CBC 11B-216.3 an	d 2010 ADAS 216.3			
As Built Description:	No ISA sign directing to	o accessible entrance			
Proposed Solution:	Provide ISA directiona	I sign indicating location of and route to acce	essible entrance		
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$250.00	BSR: 1 Necessary		
X Coordinate:	N/A	Y Coordinate: N/A Z Coo	ordinate: N/A		
Implementati	on: Priority 4	Phase Date	Status Open		
Notes:					
Field Date:	11/14/2017 Repo	rt Date: 1/9/2019 Barrier #: 14G	Hart San		
Facility:	Humboldt County DHF	IS - 605 K St, Eureka	;;		
Location:	Corridor 100C				
Official Respo	nsible: Karen Clower	, ADA Coordinator			
Consent Decr	ee: No	Paragraph: M.51 Dwg: 1 of 1			
Barrior Area					
Dairiei Area.	Signage	Remediation: Required			
	Signage Room ID Sign - No Tac				
	Room ID Sign - No Tac		visually impaired		
Barrier Type: Barrier Description:	Room ID Sign - No Tac	tile Information I for sighted people lacks tactile info for the	visually impaired		
Barrier Type: Barrier Description:	Room ID Sign - No Tac Room ID sign provided ces: CBC 11B-216.2 an	tile Information I for sighted people lacks tactile info for the	visually impaired		
Barrier Type: Barrier Description: Code Referen As Built	Room ID Sign - No Tac Room ID sign provided ces: CBC 11B-216.2 an No tactile information	tile Information I for sighted people lacks tactile info for the old 2010 ADAS 216.2			
Barrier Type: Barrier Description: Code Referen As Built Description: Proposed	Room ID Sign - No Tact Room ID sign provided ces: CBC 11B-216.2 an No tactile information Provide room ID sign v	tile Information I for sighted people lacks tactile info for the sid 2010 ADAS 216.2 provided where visual sign exists with tactile information at wall at latch side of the side of th	of door BSR: 1 Necessary		
Barrier Type: Barrier Description: Code Referen As Built Description: Proposed Solution:	Room ID Sign - No Tact Room ID sign provided ces: CBC 11B-216.2 an No tactile information Provide room ID sign v : 1 Quantity:	tile Information I for sighted people lacks tactile info for the sid 2010 ADAS 216.2 provided where visual sign exists with tactile information at wall at latch side of the side of th	of door		
Barrier Type: Barrier Description: Code Referen As Built Description: Proposed Solution: As-Built Meas	Room ID Sign - No Tace Room ID Sign provided ces: CBC 11B-216.2 and No tactile information Provide room ID sign v : 1 Quantity: N/A	tile Information I for sighted people lacks tactile info for the sid 2010 ADAS 216.2 provided where visual sign exists with tactile information at wall at latch side of the side of th	of door BSR: 1 Necessary		



Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 14H
Facility: Humboldt County DHHS - 605 K St, Eureka
Location: Corridor 100C
Official Responsible: Property Owner
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Stairways Remediation: Required
Barrier Type: Handrail - Both Sides
Barrier Description: Handrail not provided at both sides of stairway
Code References: CBC 11B-505.2 and 2010 ADAS 505.2
As Built Description: No handrail provided at both sides
Proposed Provide handrails at both sides of stairway Solution:
As-Built Meas: 5 Quantity: LF Cost Estimate: \$1,125.00 BSR: 2 Recommended
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 4 Phase Date Status Open
Notes:
Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 141
Facility: Humboldt County DHHS - 605 K St, Eureka
Location: Corridor 100C
Official Responsible: Property Owner
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Stairways Remediation: Required
Barrier Type: Contrasting Color - Exterior
Barrier Description: No contrasting color on each tread of exterior stairway
Code References: CBC 11B-504.4.1
As Built Description: Treads lack contrasting color defined as 70% contrast
Proposed Solution: Provide contrasting color on each tread
As-Built Meas: 5 Quantity: LF or T Cost Estimate: \$175.00 BSR: 2 Recommended
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 4 Phase Date Status Open
Notes:



Field Date:	11/14/2017 Repo	rt Date: 1/9/2019	Barrier #: 15A		
Facility:	Humboldt County DH	IS - 605 K St, Eureka			
Location:	Corridor 100D				
Official Respo	nsible: Property Ow	ner			
Consent Decre	ee: No	Paragraph: M.51	Dwg: 1 of 1		
Barrier Area:	Drinking Fountains	Remediati	on: Required		
Barrier Type:	Knee Clearance				
Barrier Description:	Knee clearance under	fountain not min. 27" high			
Code Referen	ces: CBC 11B-602.2 ar	d 2010 ADAS 602.2			
As Built Description:	26-7/8" high knee clea	irance where bubbler heig	ht is 33"		
Proposed Solution:	Remount existing drin	king fountain			
As-Built Meas	: 1 Quantity:	EACH Cost Estimate:	\$750.00 BSR: 1 N	lecessary	
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordinate:	N/A	
Implementati	on: Priority 3	Phase	Date	Status Open	
Notes:					
Field Date:	11/14/2017 Repo	rt Date: 1/9/2019	Barrier #: 15B		
Facility:	Humboldt County DH	IS - 605 K St, Eureka			
Location:	Corridor 100D				
Official Respo	nsible: Karen Clower	, ADA Coordinator			
Consent Decre	ee: No	Paragraph: M.51	Dwg: 1 of 1		
Barrier Area:	Signage	Remediati	on: Required		
Barrier Type:	Room ID Sign - No Tac	tile Information			
Barrier Description:	Room ID sign provided	l for sighted people lacks t	actile info for the visually i	mpaired	
Code Referen	ces: CBC 11B-216.2 ar	d 2010 ADAS 216.2			
As Built Description:	No tactile information	provided where visual sign	n exists at rooms 114, 108	, and 109	
Proposed Solution:	Provide room ID sign v	vith tactile information at	wall at latch side of door		
As-Built Meas	: 3 Quantity:	EACH Cost Estimate:	\$750.00 BSR: 1 N	lecessary	
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordinate:	N/A	
Implementati	on: Priority 4	Phase	Date	Status Closed	
Notes: CI	osed 12-07-2021 ADA				



Field Date:	11/14/2017 Report Date: 1/9/2019 Barrier #: 15C				
Facility:	Humboldt County DHHS - 605 K St, Eureka				
Location:	Corridor 100D				
Official Respo	nsible: Property Owner				
Consent Decre	ee: No Paragraph: M.51 Dwg: 1 of 1				
Barrier Area:	Alarms Remediation: Required				
Barrier Type:	Horn/Strobe - Corridor				
Barrier Description:	No horn/strobes in corridor				
Code Referen	Ces: CBC 11B-702.1 and 2010 ADAS 702.1				
As Built Description:	Device not provided				
Proposed Solution:	Provide strobes in common use area				
As-Built Meas	Quantity: EACH Cost Estimate: \$5,500.00 BSR: 1 Necessary				
X Coordinate:	N/A Y Coordinate: N/A Z Coordinate: N/A				
Implementation	on: Priority 2 Phase Date Status Exception				
Notes: Exce	ption 1 in CBC 907.5.2.3 and CBC 11B-215.1.				
Field Date:	11/14/2017 Report Date: 1/9/2019 Barrier #: 16A				
Facility:	Humboldt County DHHS - 605 K St, Eureka				
Location:	Training Classroom 110				
Official Respo	nsible: Karen Clower, ADA Coordinator				
Consent Decre	ee: No Paragraph: M.51 Dwg: 1 of 1				
Barrier Area:	Signage Remediation: Required				
Barrier Type:	Room ID Sign - No Tactile Information				
Barrier Description:	Room ID sign provided for sighted people lacks tactile info for the visually impaired				
Code Referen	Ces: CBC 11B-216.2 and 2010 ADAS 216.2				
As Built Description:	No tactile information provided where visual sign exists				
Proposed Solution:	Provide room ID sign with tactile information at wall at latch side of door				
As-Built Meas	Quantity: EACH Cost Estimate: \$250.00 BSR: 1 Necessary				
X Coordinate:	N/A Y Coordinate: N/A Z Coordinate: N/A				
Implementation	on: Priority 4 Phase Date Status Closed				
Notes: Clo	osed 12-07-2021 ADA Compliance Team. Photo in closed barrier folder.				



Field Date:	11/14/2017 Report Date: 1/9/2019 Barrier #: 16B				
Facility:	Humboldt County DHHS - 605 K St, Eureka				
Location:	Training Classroom 110				
Official Respo	nsible: Property Owner				
Consent Decr	ee: No Paragraph: M.51 Dwg: 1 of 1				
Barrier Area:	Doors or Gates Remediation: Required				
Barrier Type:	Door Closer - Interior Automatic Device				
Barrier Description:	Door opening force exceeds 5 lbf				
Code Referen	ces: CBC 11B-404.2.9 and 2010 ADAS 404.2.9				
As Built Description:	9 lbf at fire rated door				
Proposed Solution:	Provide automatic door opening device to comply with fire code requirements and access requirement				
As-Built Meas	2 Quantity: EACH Cost Estimate: \$5,000.00 BSR: 1 Necessary				
X Coordinate:	N/A Y Coordinate: N/A Z Coordinate: N/A				
Implementati	on: Priority 2 Phase Date Status Open				
Notes:					
Field Date:	11/14/2017 Report Date: 1/9/2019 Barrier #: 16C				
Facility:	Humboldt County DHHS - 605 K St, Eureka				
Location:	Training Classroom 110				
Official Respo	onsible: Property Owner				
Consent Decr	,				
	Doors or Gates Remediation: Required				
Barrier Type:	Door Closer - Interior Sweep				
Barrier Description:	Door closer lacks min. 5 second sweep period/back check				
Code Referen	ces: CBC 11B-404.2.8.1 and ADA/ABA 404.2.8.1				
As Built Description:	2 second sweep				
B					
Proposed Solution:	Provide automatic door opening device to comply with fire code requirements and access requirement				
•	requirement Cost Estimate: \$0.00 BSR: 2 Recommended				
Solution:	requirement Cost Estimate: \$0.00 BSR: 2 Recommended				
Solution: As-Built Meas	requirement SE Q Quantity: EACH Cost Estimate: \$0.00 BSR: 2 Recommended N/A Y Coordinate: N/A Z Coordinate: N/A				



Field Date:	11/14/2017 Report Date: 1/9	9/2019 Barrier #:	16D		
Facility:	Humboldt County DHHS - 605 K St, Eureka				
Location:	Training Classroom 110				
Official Respo	onsible: Karen Clower, ADA Coord	inator			
Consent Decre	ree: No Paragraph:	M.51 Dwg:	1 of 1		
Barrier Area:	Doors or Gates	Remediation: Requ	ired		
Barrier Type:	Maneuvering Cl - Stored Items				
Barrier Description:	Door/Gate lacks required maneuv	ering clearance			
Code Referen	nces: CBC Figure 11B-404.2.4.1 and	2010 ADAS 404.2.4.1			
As Built Description:	Trash bin blocks maneuvering clea	rance at pull side of doc	r		
Proposed Solution:	Remove stored items to provide a	ccess			
As-Built Meas	s: 1 Quantity: EACH Co	st Estimate: \$125.00	BSR: 1 No	ecessary	
X Coordinate:	: N/A Y Coordina	te: N/A	Z Coordinate:	N/A	
Implementati	ion: Priority 2 Phase	Date		Status Closed	
Notes:	Closed 12-07-2021 ADA Compliano	ce Team. Photo in closec	barrier folder.		
Field Date:	11/14/2017 Report Date: 1/9	9/2019 Barrier #:	16E		
Facility:	Humboldt County DHHS - 605 K St	, Eureka	350	<u> </u>	
Location:	Training Classroom 110			1 -012	
Official Respo	onsible: Karen Clower, ADA Coord	inator			
Consent Decre	ree: No Paragraph:	M.51 Dwg:	1 of 1		
Barrier Area:	Controls and Mechanisms	Remediation: Requ	ired		
Barrier Type:	Operable Part - Clear Floor Space	(Stored Items)			
Barrier Description:	Clear floor space for person using	wheelchair not provided	at operable part		
Code Referen	nces: CBC 11B-305.3 and 2010 ADA	S 305.3			
As Built Description:	Trash bin blocks electrical switch,	dispenser, and first aid k	it clear floor spac	re	
Proposed Solution:	Move stored items at control or m	nechanism			
As-Built Meas	s: 1 Quantity: JOB Co	st Estimate: \$0.00	BSR: 1 No	ecessary	
X Coordinate:	: N/A Y Coordina	te: N/A	Z Coordinate:	N/A	
Implementati	ion: Priority 2 Phase	Date		Status Closed	
Notes: Clo	osed 12-07-2021 ADA Compliance T	eam. Photo in closed ba	rrier folder.		



Field Date:	11/14/2017 Repo	rt Date: 1/9/2019	Barrier #: 16F		
Facility:	Humboldt County DHF	IS - 605 K St, Eureka	250	3 2	
Location:	Training Classroom 110				
Official Respon	nsible: Karen Clower	ADA Coordinator			
Consent Decre	ee: No	Paragraph: M.51	Dwg: 1 of 1		
Barrier Area:	Accessible Route - Inte	rior Remediat	ion: Required		
Barrier Type:	Protruding Object - Wa	all Mounted Object			
Barrier Description:	Wall mounted object ք	protrudes more than 4" in	to accessible route betwe	een 27" and 80" high	
Code Reference	ces: CBC 11B-307.2 an	d 2010 ADAS 307.2			
As Built Description:	Hand sanitizer dispens	er protrudes 4-1/2" at 45	-1/2" high		
Proposed Solution:	Remove object or prov	ride detectable warning (v	ving walls)		
As-Built Meas	1 Quantity:	EACH Cost Estimate:	\$550.00 BSR: 1	Necessary	
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordinate	e: N/A	
Implementation	on: Priority 2	Phase	Date	Status Closed	
Notes: Clos	sed 12-07-2021 ADA Co	ompliance Team. Photo in	closed barrier folder.		
Field Date:	11/14/2017 Repo	rt Date: 1/9/2019	Barrier #: 16G		
Facility:	Humboldt County DHF	IS - 605 K St, Eureka	.50	<u> </u>	
Location:	Training Classroom 11)		11 -01-	
Official Respon	nsible: Karen Clower	ADA Coordinator			
Consent Decre	ee: No	Paragraph: M.51	Dwg: 1 of 1		
	Accessible Route - Inte		ion: Required		
Barrier Type:	Protruding Object - Wa	all Mounted Object			
Barrier Description:	Wall mounted object ք	protrudes more than 4" in	to accessible route betwe	een 27" and 80" high	
Code Reference	ces: CBC 11B-307.2 an	d 2010 ADAS 307.2			
As Built Description:	First aid kit protrudes	more than 4" between 27	" - 80" high		
Proposed Solution:	Remove object or prov	ride detectable warning (v	ving walls)		
		EACH Cost Estimate:	\$550.00 BSR: 1	Necessary	
As-Built Meas	Quantity:	LACIT COSt Estimate:	5550.00 B5K. [1	Necessary	
As-Built Meas X Coordinate:		Y Coordinate: N/A	Z Coordinate		
	N/A				



Field Date:	11/14/2017 Repo	rt Date: 1/9/2019	Barrier #: 16H		
Facility:	Humboldt County DHHS - 605 K St, Eureka				
Location:	Training Classroom 110				
Official Respo	nsible: Karen Clower	, ADA Coordinator			
Consent Decre	ee: No	Paragraph: M.51	Dwg: 1 of		
Barrier Area:	Controls and Mechani	sms Remediat	ion: Required		
Barrier Type:	First Aid Kit - Reach Ra	nge			
Barrier Description:	First aid kit operating	nechanism not max. 48" l	nigh		
Code Referen	ces: CBC 11B-308.2.1	and 2010 ADAS 308.2.1			
As Built Description:	71" high				
Proposed Solution:	Replace operating con	trol on medicine cabinet			
As-Built Meas	: 1 Quantity:	EACH Cost Estimate:	\$325.00	BSR: 1 Necessary	
X Coordinate:	N/A	Y Coordinate: N/A	Z C	oordinate: N/A	
Implementati	on: Priority 2	Phase	Date	Status Closed	
Notes: Clos	sed 12-07-2021 ADA Co	mpliance Team. Photo in	closed barrier fo	lder.	
Field Date:	11/14/2017 Repo	rt Date: 1/9/2019	Barrier #: 16I		
Facility:	Humboldt County DH	IS - 605 K St, Eureka		.53	
Location:	Training Classroom 11	0		11 -0 -12	
Official Respo	nsible: Karen Clower	, ADA Coordinator			
Consent Decre	ee: No	Paragraph: M.51	Dwg: 1 of		
Barrier Area:	Controls and Mechani	sms Remediat	ion: Required		
Barrier Type:	First Aid Kit - Operatio	n			
Barrier Description:	Operable part not ope the wrist	rable with one hand and o	or requires tight	grasping, pinching, or twisting of	
Code Referen	ces: CBC 11B-309.4 ar	d 2010 ADAS 309.4			
As Built Description:	First aid kit opening co	ntrols not fist operable			
Proposed Solution:	Replace operating con	trol on medicine cabinet			
As-Built Meas	: 1 Quantity:	EACH Cost Estimate:	\$325.00	BSR: 1 Necessary	
X Coordinate:	N/A	Y Coordinate: N/A	Z C	oordinate: N/A	
Implementati		Phase	Date	Status Closed	
Notes: Clos	ed 12-07-2021 ADA Co	mpliance Team. Photo in	closed barrier fo	lder.	



Field Date:	11/14/2017 Report	Date: 1/9/2019	Barrier #: 16J		
Facility:	Humboldt County DHHS - 605 K St, Eureka				
Location:	Training Classroom 110				
Official Respo	nsible: Karen Clower, A	ADA Coordinator			
Consent Decre	ee: No P	aragraph: M.51	Dwg: 1 of 1		
Barrier Area:	Counters and Tables	Remediat	ion: Required		
Barrier Type:	Podium - Knee Clearance	e			
Barrier Description:	Podium knee clearance o	of at least 27" high, 30"	wide and 8" deep not	provided	
Code Referen	ces: CBC 11B-902.2 and	2010 ADAS 902.2			
As Built Description:	No knee clearance				
Proposed Solution:	Reposition podium to pr	rovide knee clearance			
As-Built Meas	: 1 Quantity: E	EACH Cost Estimate:	\$450.00 BSR	1 Necessary	
X Coordinate:	N/A Y	Coordinate: N/A	Z Coordii	nate: N/A	
Implementati	on: Priority 2	Phase	Date	Status Closed	
Notes: Close	ed 3-15-2021 ADA Compl	liance Team. Podium has	s been removed.		
Field Date:	11/14/2017 Report	Date: 1/9/2019	Barrier #: 16K		
Facility:	Humboldt County DHHS	- 605 K St, Eureka			
Location:	Training Classroom 110				
Official Respo	nsible: Karen Clower, A	ADA Coordinator			
Consent Decre	ee: No P	aragraph: M.51	Dwg: 1 of 1		
Barrier Area:	Counters and Tables	Remediat	ion: Required		
Barrier Type:	Podium - Work Surface				
Barrier Description:	Podium surface height e	exceeds 34" high			
Code Referen	ces: CBC 11B-902.3 and	2010 ADAS 902.3			
As Built Description:	42-3/4" high				
Proposed Solution:	Replace podium or alter	nate accessible podium			
As-Built Meas	: 1 Quantity: E	EACH Cost Estimate:	\$875.00 BSR	3 Hindrance	
X Coordinate:	N/A Y	Coordinate: N/A	Z Coordii	nate: N/A	
Implementati	on: Priority 2	Phase	Date	Status Closed	
Notes: Close	ed 3-15-2021 ADA Compli	iance Team. Podium has	been removed.		



Field Date:	11/14/2017 Repo	rt Date: 1/9/2019	Barrier #: 16L	namench .	
Facility:	Humboldt County DHHS - 605 K St, Eureka				
Location:	Training Classroom 110				
Official Respo	nsible: Karen Clower	, ADA Coordinator			
Consent Decre	ee: No	Paragraph: M.51	Dwg: 1 of 1	4	
Barrier Area:	Counters and Tables	Remediati	on: Required		
Barrier Type:	Table - Knee Clearance				
Barrier Description:	Knee clearance of at le	east 27" high, 30" wide and	1 19" deep not provided		
Code Referen	ces: CBC 11B-306.3 an	d 2010 ADAS 306.3			
As Built Description:	13-1/2" deep knee cle	arance			
Proposed Solution:	Move stored objects				
As-Built Meas	: 1 Quantity:	EACH Cost Estimate:	\$0.00 BSR: 3 H	Hindrance	
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordinate	: N/A	
Implementati	on: Priority 2	Phase	Date	Status Closed	
Notes: Close	ed 3-15-2021 ADA Com	pliance Team. Photo in clos	sed barrier folder.		
Field Date:	11/14/2017 Repo	rt Date: 1/9/2019	Barrier #: 16M	easerot .	
Facility:	Humboldt County DHF	IS - 605 K St, Eureka		1-11	
Location:	Training Classroom 11	0	i (cian		
Official Respo	nsible: Karen Clower	, ADA Coordinator			
Consent Decre	ee: No	Paragraph: M.51	Dwg: 1 of 1	-	
Barrier Area:	Classrooms	Remediati	on: Required		
Barrier Type:	Whiteboard/Chalkboa	rd - Clear Floor Space			
Barrier Description:	Clear floor space of mi	n. 30" by 48" not provided	I		
Code Referen	ces: CBC 11B-305.3 an	d 2010 ADAS 305.3			
As Built Description:	No clear floor space pr	ovided at whiteboard			
Proposed Solution:	Rearrange furniture to	provide wheelchair access	s at min. 1 whiteboard/ch	alkboard	
As-Built Meas	Quantity:	JOB Cost Estimate:	\$0.00 BSR: 1 N	lecessary	
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordinate	N/A	
Implementati	on: Priority 2	Phase	Date	Status Closed	
Notes: Clos	ed 12-07-2021 ADA Co	mpliance Team. Photo in c	closed barrier folder.		



Field Date:	11/14/2017 Repo	rt Date: 1/9/2019	Barrier #: 16N	The self of Allice	
Facility:	Humboldt County DHHS - 605 K St, Eureka				
Location:	Training Classroom 110				
Official Respo	nsible: Karen Clower	, ADA Coordinator			
Consent Decre	ee: No	Paragraph: M.51	Dwg: 1 of 1		
Barrier Area:	Classrooms	Remediat	ion: Required		
Barrier Type:	Workstation - Knee Cle	earance			
Barrier Description:	Knee clearance of at le	ast 27" high, 30" wide an	d 19" deep not provided		
Code Referen	ces: CBC 11B-306.3 an	d 2010 ADAS 306.3			
As Built Description:	21-1/2" wide knee clea	arance and 24-1/2" high k	nee clearance at 20 work	stations	
Proposed Solution:	Replace min. 1 workst	ation to provide knee clea	rance		
As-Built Meas	Quantity:	EACH Cost Estimate:	\$450.00 BSR: 1	Necessary	
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordinate	e: N/A	
Implementation	on: Priority 2	Phase	Date	Status Closed	
Notes: Close	ed 3-15-2021 ADA Com	pliance Team. Photo in cl	osed barrier folder.		
Field Date:	11/14/2017 Repo	rt Date: 1/9/2019	Barrier #: 160	To the state of th	
Facility:	Humboldt County DHF	IS - 605 K St, Eureka			
Location:	Training Classroom 11	0	-		
Official Respo	nsible: Karen Clower	ADA Coordinator		- T	
Consent Decre		Paragraph: M.51	Dwg: 1 of 1		
	Controls and Mechanis		ion: N/A		
Barrier Type:	Operable Part - Side Ro	each High (Safe Harbor)			
Barrier Description:	Operable part at max.	54" high			
Code Referen	ces: ADA Title II, Subpa	art D, § 35.150 Existing fa	cilities § 35.150(b)(2)(i)		
As Built Description:	Shelf trays 50-1/2" hig	h			
Proposed Solution:	No remediation requir harbor	ed. Control or mechanism	n complied with prior code	e and is granted safe	
As-Built Meas	Quantity:	EACH Cost Estimate:	\$0.00 BSR: 3	Hindrance	
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordinate	e: N/A	
Implementation	on: Priority 2	Phase	Date	Status Closed	
Notes:					



Field Date:	11/14/2017 Report Date: 1/9/2019 Barrier #: 16P			
Facility:	Humboldt County DHHS - 605 K St, Eureka			
Location:	Training Classroom 110			
Official Respo	nsible: Karen Clower, ADA Coordinator			
Consent Decre	ee: No Paragraph: M.51 Dwg: 1 of 1			
Barrier Area:	Controls and Mechanisms Remediation: Required			
Barrier Type:	Operable Part - Clear Floor Space (Stored Items)			
Barrier Description:	Clear floor space for person using wheelchair not provided at operable part			
Code Referen	ces: CBC 11B-305.3 and 2010 ADAS 305.3			
As Built Description:	Fan blocks printer clear floor space			
Proposed Solution:	Move stored items			
As-Built Meas	Cost Estimate: \$0.00 BSR: 1 Necessary			
X Coordinate:	N/A Y Coordinate: N/A Z Coordinate: N/A			
Implementati	on: Priority 2 Phase Date Status Closed			
Notes: Clo	sed 12-07-2021 ADA Compliance Team. Photo in closed barrier folder.			
Field Date:	11/14/2017 Report Date: 1/9/2019 Barrier #: 16Q			
Facility:	Humboldt County DHHS - 605 K St, Eureka			
Location:	Training Classroom 110			
Official Respo	nsible: Karen Clower, ADA Coordinator			
Consent Decre	ee: No Paragraph: M.51 Dwg: 1 of 1			
Barrier Area:	Controls and Mechanisms Remediation: N/A			
Barrier Type:	Operable Part - Side Reach High (Safe Harbor)			
Barrier Description:	Operable part at max. 54" high			
Code Referen	ces: ADA Title II, Subpart D, § 35.150 Existing facilities § 35.150(b)(2)(i)			
As Built Description:				
	Printer 48-1/4" high			
Proposed Solution:	Printer 48-1/4" high No remediation required. Control or mechanism complied with prior code and is granted safe harbor			
•	No remediation required. Control or mechanism complied with prior code and is granted safe harbor			
Solution:	No remediation required. Control or mechanism complied with prior code and is granted safe harbor 1			
Solution: As-Built Meas	No remediation required. Control or mechanism complied with prior code and is granted safe harbor I Quantity: EACH Cost Estimate: \$0.00 BSR: 3 Hindrance N/A Y Coordinate: N/A Z Coordinate: N/A			



Field Date:	11/14/2017 Repo	rt Date: 1/9/2019 Barrier #: 16R		
Facility:	Humboldt County DHHS - 605 K St, Eureka			
Location:	Training Classroom 110			
Official Respo	nsible: Property Ow	ner		
Consent Decr	ee: No	Paragraph: M.51 Dwg: 1 of	1	
Barrier Area:	Alarms	Remediation: Required		
Barrier Type:	Horn/Strobe - Classroo	om		
Barrier Description:	No horn/strobes in cla	ssroom		
Code Referen	ces: CBC 11B-702.1 ar	d 2010 ADAS 702.1		
As Built Description:	Device not provided			
Proposed Solution:	Provide strobes in con	nmon use area		
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$5,500.00	BSR: 1 Necessary	
X Coordinate:	N/A	Y Coordinate: N/A Z C	oordinate: N/A	
Implementati	on: Priority 2	Phase Date	Status Exception	
Notes: Exce	ption 1 in CBC 907.5.2.	3 and CBC 11B-215.1.		
Field Date:	11/14/2017 Repo	rt Date: 1/9/2019 Barrier #: 17A	-6	
Facility:	Humboldt County DHI	IS - 605 K St, Eureka		
Location:	Corridor 100E			
Official Respo	nsible: Karen Clower	, ADA Coordinator		
Consent Decre	ee: No	Paragraph: M.51 Dwg: 1 of	1	
Barrier Area:	Signage	Remediation: Required		
Barrier Type:	Room ID Sign - No Tac	tile Information		
Barrier Description:	Room ID sign provided	l for sighted people lacks tactile info for th	e visually impaired	
Code Referen	ces: CBC 11B-216.2 ar	d 2010 ADAS 216.2		
As Built Description:	No tactile information and 116	provided where visual sign exists at room	s 114, 105, 106, 107, 108, 115	
Proposed Solution:	Provide room ID sign v	vith tactile information at wall at latch side	e of door	
As-Built Meas	: 7 Quantity:	EACH Cost Estimate: \$1,750.00	BSR: 1 Necessary	
X Coordinate:	N/A	Y Coordinate: N/A Z C	oordinate: N/A	
Implementati	on: Priority 4	Phase Date	Status Closed	
Notes: Clo	osed 12-07-2021 ADA C	ompliance Team. Photo in closed barrier f	folder.	



Field Date:	11/14/2017 Repo	rt Date: 1/9/2019 Barrier #: 17B	
Facility:	Humboldt County DH	HS - 605 K St, Eureka	9
Location:	Corridor 100E		
Official Respo	nsible: Property Owi	ner	
Consent Decre	ee: No	Paragraph: M.51 Dwg: 1 of 1	
Barrier Area:	Alarms	Remediation: Required	
Barrier Type:	Strobe - Location belo	w 80"	
Barrier Description:	Strobe mounted belov	v 80" AFF	
Code Referen	ces: NFPA 72 7.5.4.1		
As Built Description:	79" high. Strobe too cl	ose to eye level. Could result in seizures	
Proposed Solution:	Relocate strobe to cor	npliant height	
As-Built Meas	Quantity:	EACH Cost Estimate: \$5,500.00 BSR: 1 N	ecessary
X Coordinate:	N/A	Y Coordinate: N/A Z Coordinate:	N/A
Implementati	on: Priority 2	Phase Date	Status Open
Notes:			
Field Date:	11/14/2017 Repo	rt Date: 1/9/2019 Barrier #: 18A	
Facility:	Humboldt County DHI	HS - 605 K St, Eureka	
Location:	Women's Restroom		
Official Respo	nsible: Property Own	ner	
Consent Decre	ee: No	Paragraph: M.51 Dwg: 1 of 1	7
Barrier Area:	Restrooms	Remediation: Required	
Barrier Type:	Sign - 12" Circle/triang	le with Braille	
Barrier Description:	12" geometric door si	gn incorrectly has raised text or Braille on door sign	
Code Referen	ces: CBC 11B-703.7.2.	6	
As Built Description:	Door sign contains Bra	ille or tactile characters	
Proposed Solution:	Provide new sign with	out text raised or Braille	
As-Built Meas	Quantity:	EACH Cost Estimate: \$250.00 BSR: 1 N	ecessary
X Coordinate:	N/A	Y Coordinate: N/A Z Coordinate:	N/A
Implementati	on: Priority 3	Phase Date	Status Closed
Notes: Clos	ed 12/07/2021 ADA Co	mpliance team. Photo in closed barrier folder.	



Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 18B
Facility: Humboldt County DHHS - 605 K St, Eureka
Location: Women's Restroom
Official Responsible: Property Owner
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Doors or Gates Remediation: Required
Barrier Type: Door Closer - Interior Adjustment
Barrier Door opening force exceeds 5 lbf Description:
Code References: CBC 11B-404.2.9 and 2010 ADAS 404.2.9
As Built Description: 11 lbf at non-fire rated door
Proposed Solution: Per US DOJ, door closer can be removed to comply. If closer remains, adjust or replace to provide max. 5 lbf
As-Built Meas: 0 Quantity: EACH Cost Estimate: \$0.00 BSR: 1 Necessary
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 3 Phase Date Status Open
Notes:
Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 18C
Facility: Humboldt County DHHS - 605 K St, Eureka
Location: Women's Restroom
Official Responsible: Property Owner
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Doors or Gates Remediation: Required
Barrier Type: Door Closer - Interior Sweep
Barrier Description: Door closer lacks min. 5 second sweep period/back check
Code References: CBC 11B-404.2.8.1 and ADA/ABA 404.2.8.1
As Built 1 second sweep at non-fire rated door Description:
Proposed Solution: Per US DOJ, door closer can be removed to comply. If closer remains, adjust or replace to provide max. 5 lbf
As-Built Meas: 0 Quantity: EACH Cost Estimate: \$0.00 BSR: 1 Necessary
As-Built Meas: 0 Quantity: EACH Cost Estimate: \$0.00 BSR: 1 Necessary X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A



Field Date:	11/14/2017 Report Date: 1/9/2019 Barrier #: 18D			
Facility:	Humboldt County DHHS - 605 K St, Eureka			
Location:	Women's Restroom			
Official Respo	nsible: Property Owner			
Consent Decre	ee: No Paragraph: M.51 Dwg: 1 of 1			
Barrier Area:	Doors or Gates Remediation: Required			
Barrier Type:	Smooth Surface at Bottom - Doorstop			
Barrier Description:	Door/Gate has door stop that may create trap condition			
Code Referen	CBC 11B-404.2.10 and 2010 ADAS 404.2.3, 404.2.10			
As Built Description:	Door stop located within bottom 10" of door			
Proposed Solution:	Remove door stop or any other element within bottom 10" of door			
As-Built Meas	Quantity: EACH Cost Estimate: \$225.00 BSR: 1 Necessary			
X Coordinate:	N/A Y Coordinate: N/A Z Coordinate: N/A			
Implementation	on: Priority 3 Phase Date Status Open			
Notes:				
Field Date:	11/14/2017 Report Date: 1/9/2019 Barrier #: 18E			
Facility:	Humboldt County DHHS - 605 K St, Eureka			
Location:	Women's Restroom			
Official Respo	nsible: Property Owner			
Official Response				
Consent Decre Barrier Area:	Paragraph: M.51 Controls and Mechanisms Remediation: N/A			
Consent Decre Barrier Area:	ee: No Paragraph: M.51 Dwg: 1 of 1			
Consent Decre Barrier Area:	Paragraph: M.51 Controls and Mechanisms Remediation: N/A			
Consent Decre Barrier Area: Barrier Type: Barrier Description:	Controls and Mechanisms Remediation: N/A Electrical Switches - Side Reach High (Safe Harbor)			
Consent Decre Barrier Area: Barrier Type: Barrier Description:	Paragraph: M.51 Dwg: 1 of 1 Controls and Mechanisms Remediation: N/A Electrical Switches - Side Reach High (Safe Harbor) Light switch control box top edge at max. 54" high measured to top of box			
Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed	Paragraph: M.51 Dwg: 1 of 1 Controls and Mechanisms Remediation: N/A Electrical Switches - Side Reach High (Safe Harbor) Light switch control box top edge at max. 54" high measured to top of box Ces: ADA Title II, Subpart D, § 35.150 Existing facilities § 35.150(b)(2)(i)			
Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed	Controls and Mechanisms Remediation: N/A Electrical Switches - Side Reach High (Safe Harbor) Light switch control box top edge at max. 54" high measured to top of box Ces: ADA Title II, Subpart D, § 35.150 Existing facilities § 35.150(b)(2)(i) 52-1/8" high No remediation required. Control or mechanism complied with prior code and is granted safe harbor			
Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed Solution:	Controls and Mechanisms Remediation: N/A Electrical Switches - Side Reach High (Safe Harbor) Light switch control box top edge at max. 54" high measured to top of box Ces: ADA Title II, Subpart D, § 35.150 Existing facilities § 35.150(b)(2)(i) 52-1/8" high No remediation required. Control or mechanism complied with prior code and is granted safe harbor 1 Quantity: EACH Cost Estimate: \$0.00 BSR: 4 Low Severity N/A Y Coordinate: N/A Z Coordinate: N/A			
Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed Solution: As-Built Meas	Controls and Mechanisms Remediation: N/A Electrical Switches - Side Reach High (Safe Harbor) Light switch control box top edge at max. 54" high measured to top of box Ces: ADA Title II, Subpart D, § 35.150 Existing facilities § 35.150(b)(2)(i) 52-1/8" high No remediation required. Control or mechanism complied with prior code and is granted safe harbor 1 Quantity: EACH Cost Estimate: \$0.00 BSR: 4 Low Severity N/A Y Coordinate: N/A Z Coordinate: N/A			



Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 18F
Facility: Humboldt County DHHS - 605 K St, Eureka
Location: Women's Restroom
Official Responsible: Karen Clower, ADA Coordinator
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Restrooms Remediation: Required
Barrier Type: Dispensers - Protruding Object
Barrier Dispenser creates protruding object in path of travel Description:
Code References: CBC 11B-307.2 and 2010 ADAS 307.2
As Built Hand sanitizer dispenser protrudes 4-1/2" at 45" high Description:
Proposed Provide detectable warning Solution:
As-Built Meas: 0 Quantity: SF Cost Estimate: \$0.00 BSR: 1 Necessary
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 3 Phase Date Status Open
Notes:
Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 18G
Facility: Humboldt County DHHS - 605 K St, Eureka
Location: Women's Restroom
Official Responsible: Property Owner
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Restrooms Remediation: Required
Barrier Type: Shelf - Protruding Object
Barrier Shelf protrudes more than 4" from wall in circulation path Description:
Code References: CBC 11B-307.2 and 2010 ADAS 307.2
As Built Shelf protrudes 6" at 45-1/2" high Description:
Proposed Provide detectable warning or move shelf Solution:
As-Built Meas: 1 Quantity: JOB Cost Estimate: \$500.00 BSR: 1 Necessary
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 3 Phase Date Status Open
Notes:



Field Date:	11/14/2017 Repo	rt Date: 1/9/2019	Barrier #: 18H	
Facility:	Humboldt County DHF	IS - 605 K St, Eureka		
Location:	Women's Restroom			
Official Respon	nsible: Property Own	ner		Mal.
Consent Decre	ee: No	Paragraph: M.51	Dwg: 1 of 1	
Barrier Area:	Restrooms	Remedia	tion: Required	
Barrier Type:	Mirror - Bottom Edge			
Barrier Description:	Mirror at lavatory/cou	ntertop not max. 40" AFF	at edge of reflecting s	urface
Code Reference	ces: CBC 11B-603.3 an	d 2010 ADAS 603.3		
As Built Description:	51-1/8" high			
Proposed Solution:	Provide min. one acce	ssible mirror at lavatory o	or dressing counter	
As-Built Meas	Quantity:	EACH Cost Estimate:	\$375.00 BSR:	3 Hindrance
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordir	nate: N/A
Implementation	on: Priority 3	Phase	Date	Status Open
Notes:				
Field Date:	11/14/2017 Repo	rt Date: 1/9/2019	Barrier #: 18I	
Facility:	Humboldt County DHF	IS - 605 K St, Eureka		
Location:	Women's Restroom			
Official Respon	nsible: Karen Clower	ADA Coordinator		No.
Consent Decre		Paragraph: M.51	Dwg: 1 of 1	
Barrier Area:	Restrooms	Remedia	tion: Required	
Barrier Type:	Dispensers - Control P	oint		
Barrier Description:	Dispenser control poir	t or operating mechanisr	n not max. 40" AFF	
Code Reference	ces: CBC 11B-603.5			
As Built Description:	Paper towel dispenser	s 44-3/4" and 55" high		
Proposed				
Solution:	Replace or remount di	spensers		
Solution: As-Built Meas	<u> </u>	EACH Cost Estimate:	\$250.00 BSR:	2 Recommended
I	Quantity:			2 Recommended nate: N/A
As-Built Meas	Quantity:	EACH Cost Estimate:		



Field Date:	11/14/2017 Repo	rt Date: 1/9/2019 Barrier #: 18J		
Facility:	Humboldt County DHF	IS - 605 K St, Eureka		
Location:	Women's Restroom			
Official Respo	nsible: Karen Clower	, ADA Coordinator	M. J.	
Consent Decre	ee: No	Paragraph: M.51 Dwg: 1 of 1		
Barrier Area:	Restrooms	Remediation: Required		
Barrier Type:	Dispensers - Protrudin	g Object		
Barrier Description:	Dispenser creates prot	truding object in path of travel		
Code Referen	ces: CBC 11B-307.2 an	id 2010 ADAS 307.2		
As Built Description:	Paper towel dispenser	s protrude 8" at 44-3/4" and 55" high		
Proposed Solution:	Relocate/remount disp	pensers or provide detectable warning		
As-Built Meas	: 0 Quantity:	EACH Cost Estimate: \$0.00 BS	R: 2 Recommended	
X Coordinate:	N/A	Y Coordinate: N/A Z Coor	dinate: N/A	
Implementati	on: Priority 3	Phase Date	Status Open	
Notes:				
Field Date:	11/14/2017 Repo	rt Date: 1/9/2019 Barrier #: 18K		
Field Date: Facility:	11/14/2017 Repo			
Facility:	Humboldt County DHF Women's Restroom	HS - 605 K St, Eureka		
Facility: Location:	Humboldt County DHF Women's Restroom nsible: Property Owr	HS - 605 K St, Eureka		
Facility: Location: Official Respo Consent Decre Barrier Area:	Humboldt County DHI- Women's Restroom nsible: Property Owr ee: No Restrooms	HS - 605 K St, Eureka		
Facility: Location: Official Respo Consent Decre Barrier Area:	Humboldt County DHH Women's Restroom nsible: Property Owr ee: No	ner Paragraph: M.51 Dwg: 1 of 1		
Facility: Location: Official Respo Consent Decre Barrier Area:	Humboldt County DHI Women's Restroom nsible: Property Owr ee: No Restrooms Self-closing Door	ner Paragraph: M.51 Dwg: 1 of 1		
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description:	Humboldt County DHI- Women's Restroom nsible: Property Owr ee: No Restrooms Self-closing Door Stall door or restroom	ner Paragraph: M.51 Remediation: Required		
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description:	Humboldt County DHI- Women's Restroom nsible: Property Owr ee: No Restrooms Self-closing Door Stall door or restroom	Paragraph: M.51 Dwg: 1 of 1 Remediation: Required entry door not equipped with a closing device 2 and 2010 ADAS 603.8.1.2		
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built	Humboldt County DHI- Women's Restroom nsible: Property Own ee: No Restrooms Self-closing Door Stall door or restroom ces: CBC 11B-604.8.1.2 Stall door not self-clos	Paragraph: M.51 Dwg: 1 of 1 Remediation: Required entry door not equipped with a closing device 2 and 2010 ADAS 603.8.1.2		
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed	Humboldt County DHI- Women's Restroom nsible: Property Own ee: No Restrooms Self-closing Door Stall door or restroom ces: CBC 11B-604.8.1.2 Stall door not self-clos Replace compartment	her Paragraph: M.51 Dwg: 1 of 1 Remediation: Required entry door not equipped with a closing device 2 and 2010 ADAS 603.8.1.2 ing hinge with adjustable mechanism	R: 2 Recommended	
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed Solution:	Humboldt County DHI- Women's Restroom nsible: Property Owr ee: No Restrooms Self-closing Door Stall door or restroom ces: CBC 11B-604.8.1.2 Stall door not self-clos Replace compartment : 1 Quantity:	Paragraph: M.51 Dwg: 1 of 1 Remediation: Required entry door not equipped with a closing device 2 and 2010 ADAS 603.8.1.2 ing hinge with adjustable mechanism JOB Cost Estimate: \$240.00 BS		
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed Solution: As-Built Meas	Humboldt County DHI- Women's Restroom nsible: Property Owr ee: No Restrooms Self-closing Door Stall door or restroom ces: CBC 11B-604.8.1.2 Stall door not self-clos Replace compartment : 1 Quantity: N/A	Paragraph: M.51 Dwg: 1 of 1 Remediation: Required entry door not equipped with a closing device 2 and 2010 ADAS 603.8.1.2 ing hinge with adjustable mechanism JOB Cost Estimate: \$240.00 BS	SR: 2 Recommended	



Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 18L	71
Facility: Humboldt County DHHS - 605 K St, Eureka	11 1
Location: Women's Restroom	
Official Responsible: Property Owner	
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1	
Barrier Area: Restrooms Remediation: Required	
Barrier Type: Stall Door Hardware - Outer U-pull	
Barrier Description: Outside of compartment door lacks a loop or U-pull below latch	
Code References: CBC 11B-604.8.1.2 and 2010 ADAS 603.8.1.2	
As Built Description: No u-pull provided on either side of door	
Proposed Solution: Provide compliant hardware	
As-Built Meas: 1 Quantity: EACH Cost Estimate: \$300.00 BSR: 1 Necessary	
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A	
Implementation: Priority 3 Phase Date Status Open	
Notes:	
Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 18M	
Facility: Humboldt County DHHS - 605 K St, Eureka	
Location: Women's Restroom	
Official Responsible: Property Owner	
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1	
Barrier Area: Restrooms Remediation: Required	
Barrier Type: Stall Door Hardware - Inner U-pull	
Barrier Inside of compartment door lacks a loop or U-pull below latch Description:	
Code References: CBC 11B-604.8.1.2 and 2010 ADAS 603.8.1.2	
As Built Description: No u-pull provided on inside of door	
Proposed Solution: Provide compliant hardware	
As-Built Meas: 1 Quantity: EACH Cost Estimate: \$300.00 BSR: 1 Necessary	
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A	
Implementation: Priority 3 Phase Date Status Open	
Notes:	



Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 18N
Facility: Humboldt County DHHS - 605 K St, Eureka
Location: Women's Restroom
Official Responsible: Property Owner
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Restrooms Remediation: Required
Barrier Type: Clothing Hooks - Height
Barrier Clothing hooks not max. 48" high AFF Description:
Code References: CBC 11B-603.4, 11B-308.2.1 & 2010 ADA 603.4
As Built 59-3/4" high Description:
Proposed Solution: Provide additional hook in compliant location
As-Built Meas: 1 Quantity: EACH Cost Estimate: \$125.00 BSR: 2 Recommended
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 3 Phase Date Status Open
Notes:
Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 180
Facility: Humboldt County DHHS - 605 K St, Eureka
Location: Women's Restroom
Official Responsible: Property Owner
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Restrooms Remediation: Required
Barrier Type: WC - Rear Grab Bar Location
Barrier Description: Rear grab bar not centered 12" from wall and 24" on the other side of WC
Code References: CBC 11B-604.5.2 and 2010 ADAS 604.5.2
As Built 15-1/4" OC Description:
Proposed Solution: Provide compliant grab bars with required reinforcement
As-Built Meas: 1 Quantity: JOB Cost Estimate: \$1,450.00 BSR: 3 Hindrance
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 3 Phase Date Status Open



Field Date:	11/14/2017 Repo	rt Date: 1/9/2019	Barrier #: 18P	
Facility:	Humboldt County DHHS - 605 K St, Eureka			
Location:	Women's Restroom			
Official Respo	nsible: Property Ow	ner		
Consent Decr	ee: No	Paragraph: M.51	Dwg: 1 of 1	
Barrier Area:	Restrooms	Remedia	tion: Required	
Barrier Type:	WC - Side Grab Bar Ex	tension		
Barrier Description:	Side grab bar does no	t extend min. 54" from re	ar wall or 24" from froi	nt rim
Code Referen	ces: CBC 11B-604.5.1	and 2010 ADAS 604.5.1		
As Built Description:	53-1/4" from rear wal	I		
Proposed Solution:	Provide compliant gra	b bars with required rein	forcement	
As-Built Meas	: 1 Quantity:	JOB Cost Estimate:	\$1,450.00 BSR:	3 Hindrance
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordir	nate: N/A
Implementati	on: Priority 3	Phase	Date	Status Open
Notes:				
Field Date:	11/14/2017 Repo	rt Date: 1/9/2019	Barrier #: 18Q	
Facility:	Humboldt County DH	HS - 605 K St, Eureka		
Location:	Women's Restroom			
Official Respo	nsible: Karen Clower	, ADA Coordinator		
Consent Decr	ee: No	Paragraph: M.51	Dwg: 1 of 1	
Barrier Area:	Restrooms	Remedia	tion: Required	and the state of t
Barrier Type:	Toilet Paper Dispense	r - Above Grab Bar		
Barrier Description:	Toilet tissue dispenser	mounted above the gral	o bar within 12" of bar	
Code Referen	ces: CBC 11B-604.5 &	609.3 and 2010 ADAS 60	4.5 & 609.3	
As Built Description:	8-3/4" between toilet	tissue dispenser and side	grab bar	
Proposed Solution:	Reposition or replace	toilet paper dispenser		
As-Built Meas	: 1 Quantity:	EACH Cost Estimate:	\$225.00 BSR:	2 Recommended
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordir	nate: N/A
Implementati	on: Priority 3	Phase	Date	Status Open
Notes:				



Field Date:	11/14/2017 Repo	rt Date: 1/9/2019	Barrier #: 18R	
Facility:	Humboldt County DH	IS - 605 K St, Eureka		
Location:	Women's Restroom			
Official Respo	nsible: Karen Clower	, ADA Coordinator		
Consent Decr	ee: No	Paragraph: M.51	Dwg: 1 of 1	
Barrier Area:	Restrooms	Remediati	ion: Required	MANAGEMENT OF THE STREET OF TH
Barrier Type:	Toilet Paper Dispense	- Height		
Barrier Description:	Toilet tissue dispenser	outlet not mounted no lo	wer than 19" from floor	
Code Referen	ces: CBC 11B-604.7 (2	010 ADAS 604.7 less string	gent)	
As Built Description:	43" high and above sid	le grab bar		
Proposed Solution:	Reposition or replace	toilet paper dispenser		
As-Built Meas	: 0 Quantity:	EACH Cost Estimate:	\$0.00 BSR: 3	Hindrance
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordinat	e: N/A
Implementati	on: Priority 3	Phase	Date	Status Open
Notes:				
Field Date:	11/14/2017 Repo	rt Date: 1/9/2019	Barrier #: 18S	
Facility:	Humboldt County DH	IS - 605 K St, Eureka		
Location:	Women's Restroom			
Official Respo	nsible: Property Ow			
Consent Decr	ee: No	Paragraph: M.51	Dwg: 1 of 1	
Barrier Area:	Restrooms	Remediati	ion: Required	PETROLOGICA DE LA CONTRACTORIA D
Barrier Type:	WC - Flush Controls Lo	cation		
Barrier Description:	Flush controls does no	t point to wide side of stal	ll or compartment	
Code Referen	ces: CBC 11B-604.6 ar	d 2010 ADAS 604.6		
As Built Description:	Handle points towards	wall or partition		
Proposed Solution:	Provide min. one acce	ssible water closet		
As-Built Meas	: 1 Quantity:	JOB Cost Estimate:	\$850.00 BSR: 1	Necessary
X Coordinate:	Ν/Δ	Y Coordinate: N/A	Z Coordinat	e: N/A
	IIV/A			, ,
Implementati	, .	Phase	Date	Status Open



Field Date:	11/14/2017 Repo	rt Date: 1/9/2019 Barrier #: 18T			
Facility:	Humboldt County DHHS - 605 K St, Eureka				
Location:	Women's Restroom				
Official Respo	nsible: Karen Clower	, ADA Coordinator			
Consent Decr	ee: No	Paragraph: M.51 Dwg: 1 of 1			
Barrier Area:	Restrooms	Remediation: Required			
Barrier Type:	Seat Cover Dispensers	- Above Toilet			
Barrier Description:	Seat cover dispenser of access	ontrol point or operating mechanism not max. 40	" AFF and toilet blocks		
Code Referen	ces: CBC 11B-603.5				
As Built Description:	Seat cover control poi	nt higher than 40" and clear floor space at dispens	ser is blocked by toilet		
Proposed Solution:	Replace or remount d	spenser			
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$125.00 BSR:	2 Recommended		
X Coordinate:	N/A	Y Coordinate: N/A Z Coordina	ite: N/A		
Implementati	on: Priority 3	Phase Date	Status Open		
Notes:					
Field Date:	11/14/2017 Repo	rt Date: 1/9/2019 Barrier #: 19A			
Facility:	Humboldt County DHI	dS - 605 K St, Eureka	<u>A</u> 2		
Location:	Men's Restroom				
Official Respo	nsible: Property Ow	ner	WALL OF		
Consent Decr	ee: No	Paragraph: M.51 Dwg: 1 of 1			
Barrier Area:	Restrooms	Remediation: Required			
Barrier Type:	Sign - 12" Circle/trians	le with Braille			
Barrier Description:	12" geometric door si	gn incorrectly has raised text or Braille on door sig	n		
Code Referen	ces: CBC 11B-703.7.2.	6			
As Built Description:	Door sign contains Bra	ille or tactile characters			
Proposed Solution:	Provide new sign with	out text raised or Braille			
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$250.00 BSR:	1 Necessary		
X Coordinate:	N/A	Y Coordinate: N/A Z Coordina	ite: N/A		
Implementati	on: Priority 3	Phase Date	Status Closed		
Notes:	Closed 12/07/2021 ADA	Compliance team. Photo in closed barrier folder.			



Field Date:	11/14/2017 Report Date: 1/9/2019 Barrier #: 19B
Facility:	Humboldt County DHHS - 605 K St, Eureka
Location:	Men's Restroom
Official Respo	nsible: Property Owner
Consent Decre	ee: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area:	Doors or Gates Remediation: Required
Barrier Type:	Door Closer - Interior Adjustment
Barrier Description:	Door opening force exceeds 5 lbf
Code Referen	ces: CBC 11B-404.2.9 and 2010 ADAS 404.2.9
As Built Description:	13 lbf at non-fire rated door
Proposed Solution:	Per US DOJ, door closer can be removed to comply. If closer remains, adjust or replace to provide max. 5 lbf
As-Built Meas	
X Coordinate:	N/A Y Coordinate: N/A Z Coordinate: N/A
Implementati	on: Priority 3 Phase Date Status Open
Notes:	
Field Date:	11/14/2017 Report Date: 1/9/2019 Barrier #: 19C
Field Date: Facility:	11/14/2017 Report Date: 1/9/2019 Barrier #: 19C Humboldt County DHHS - 605 K St, Eureka
Facility:	Humboldt County DHHS - 605 K St, Eureka Men's Restroom
Facility: Location:	Humboldt County DHHS - 605 K St, Eureka Men's Restroom nsible: Property Owner
Facility: Location: Official Respo Consent Decre	Humboldt County DHHS - 605 K St, Eureka Men's Restroom nsible: Property Owner
Facility: Location: Official Respo Consent Decre Barrier Area:	Humboldt County DHHS - 605 K St, Eureka Men's Restroom nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1
Facility: Location: Official Respo Consent Decre Barrier Area:	Humboldt County DHHS - 605 K St, Eureka Men's Restroom nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Remediation: Required
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description:	Humboldt County DHHS - 605 K St, Eureka Men's Restroom nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Remediation: Required Door Closer - Interior Sweep
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description:	Humboldt County DHHS - 605 K St, Eureka Men's Restroom nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Remediation: Required Door Closer - Interior Sweep Door closer lacks min. 5 second sweep period/back check
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Referen As Built	Humboldt County DHHS - 605 K St, Eureka Men's Restroom nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Door Closer - Interior Sweep Door closer lacks min. 5 second sweep period/back check ces: CBC 11B-404.2.8.1 and ADA/ABA 404.2.8.1
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Referen As Built Description: Proposed	Humboldt County DHHS - 605 K St, Eureka Men's Restroom nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Door Closer - Interior Sweep Door closer lacks min. 5 second sweep period/back check ces: CBC 11B-404.2.8.1 and ADA/ABA 404.2.8.1 2 second sweep Per US DOJ, door closer can be removed to comply. If closer remains, adjust or replace to provide max. 5 lbf
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Referen As Built Description: Proposed Solution:	Humboldt County DHHS - 605 K St, Eureka Men's Restroom nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Remediation: Required Door Closer - Interior Sweep Door closer lacks min. 5 second sweep period/back check ces: CBC 11B-404.2.8.1 and ADA/ABA 404.2.8.1 2 second sweep Per US DOJ, door closer can be removed to comply. If closer remains, adjust or replace to provide max. 5 lbf : O Quantity: EACH Cost Estimate: \$0.00 BSR: 1 Necessary
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Referen As Built Description: Proposed Solution: As-Built Meas	Humboldt County DHHS - 605 K St, Eureka Men's Restroom nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Remediation: Required Door Closer - Interior Sweep Door closer lacks min. 5 second sweep period/back check ces: CBC 11B-404.2.8.1 and ADA/ABA 404.2.8.1 2 second sweep Per US DOJ, door closer can be removed to comply. If closer remains, adjust or replace to provide max. 5 lbf : O Quantity: EACH Cost Estimate: \$0.00 BSR: 1 Necessary N/A Y Coordinate: N/A Z Coordinate: N/A



Field Date:	11/14/2017 Report Date: 1/9/2019 Barrier #: 19D
Facility:	Humboldt County DHHS - 605 K St, Eureka
Location:	Men's Restroom
Official Respo	nsible: Property Owner
Consent Decre	ee: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area:	Doors or Gates Remediation: Required
Barrier Type:	Smooth Surface at Bottom - Doorstop
Barrier Description:	Door/Gate has door stop that may create trap condition
Code Referen	CBC 11B-404.2.10 and 2010 ADAS 404.2.3, 404.2.10
As Built Description:	Door stop located within bottom 10" of door
Proposed Solution:	Remove door stop or any other element within bottom 10" of door
As-Built Meas	Quantity: EACH Cost Estimate: \$50.00 BSR: 1 Necessary
X Coordinate:	N/A Y Coordinate: N/A Z Coordinate: N/A
Implementati	on: Priority 3 Phase Date Status Open
Notes:	
Field Date:	11/14/2017 Report Date: 1/9/2019 Barrier #: 19E
Field Date: Facility:	11/14/2017 Report Date: 1/9/2019 Barrier #: 19E Humboldt County DHHS - 605 K St, Eureka
Facility:	
Facility:	Humboldt County DHHS - 605 K St, Eureka Men's Restroom
Facility: Location:	Humboldt County DHHS - 605 K St, Eureka Men's Restroom nsible: Karen Clower, ADA Coordinator
Facility: Location: Official Respo Consent Decre Barrier Area:	Humboldt County DHHS - 605 K St, Eureka Men's Restroom nsible: Karen Clower, ADA Coordinator ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Remediation: Required
Facility: Location: Official Respo Consent Decre Barrier Area:	Humboldt County DHHS - 605 K St, Eureka Men's Restroom nsible: Karen Clower, ADA Coordinator ee: No Paragraph: M.51 Dwg: 1 of 1
Facility: Location: Official Respo Consent Decre Barrier Area:	Humboldt County DHHS - 605 K St, Eureka Men's Restroom nsible: Karen Clower, ADA Coordinator ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Remediation: Required
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description:	Humboldt County DHHS - 605 K St, Eureka Men's Restroom nsible: Karen Clower, ADA Coordinator ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Remediation: Required Maneuvering Cl - Stored Items
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description:	Humboldt County DHHS - 605 K St, Eureka Men's Restroom nsible: Karen Clower, ADA Coordinator ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Remediation: Required Maneuvering Cl - Stored Items Door/Gate lacks required maneuvering clearance
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built	Humboldt County DHHS - 605 K St, Eureka Men's Restroom nsible: Karen Clower, ADA Coordinator ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Maneuvering Cl - Stored Items Door/Gate lacks required maneuvering clearance Ces: CBC Figure 11B-404.2.4.1 and 2010 ADAS 404.2.4.1
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Referent As Built Description: Proposed	Humboldt County DHHS - 605 K St, Eureka Men's Restroom nsible: Karen Clower, ADA Coordinator ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Maneuvering CI - Stored Items Door/Gate lacks required maneuvering clearance ces: CBC Figure 11B-404.2.4.1 and 2010 ADAS 404.2.4.1 Trash bin blocks maneuvering clearance at pull side of door Move trash bin to ensure that maneuvering clearance required at all elements is not blocked
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Referent As Built Description: Proposed Solution:	Humboldt County DHHS - 605 K St, Eureka Men's Restroom nsible: Karen Clower, ADA Coordinator ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Remediation: Required Maneuvering CI - Stored Items Door/Gate lacks required maneuvering clearance ces: CBC Figure 11B-404.2.4.1 and 2010 ADAS 404.2.4.1 Trash bin blocks maneuvering clearance at pull side of door Move trash bin to ensure that maneuvering clearance required at all elements is not blocked El Quantity: EACH Cost Estimate: \$125.00 BSR: 1 Necessary
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed Solution: As-Built Meas	Humboldt County DHHS - 605 K St, Eureka Men's Restroom nsible: Karen Clower, ADA Coordinator ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Maneuvering CI - Stored Items Door/Gate lacks required maneuvering clearance ces: CBC Figure 11B-404.2.4.1 and 2010 ADAS 404.2.4.1 Trash bin blocks maneuvering clearance at pull side of door Move trash bin to ensure that maneuvering clearance required at all elements is not blocked 1 Quantity: EACH Cost Estimate: \$125.00 BSR: 1 Necessary N/A Y Coordinate: N/A Z Coordinate: N/A



Field Date:	11/14/2017 Repo	ort Date: 1/9/2019 Barrier #: 19F
Facility:	Humboldt County DH	HS - 605 K St, Eureka
Location:	Men's Restroom	
Official Respo	nsible: Karen Clower	r, ADA Coordinator
Consent Decr	ee: No	Paragraph: M.51 Dwg: 1 of 1
Barrier Area:	Controls and Mechani	sms Remediation: Required
Barrier Type:	Operable Part - Clear F	Floor Space (Stored Items)
Barrier Description:	Clear floor space for p	erson using wheelchair not provided at operable part
Code Referen	ces: CBC 11B-305.3 ar	nd 2010 ADAS 305.3
As Built Description:	Trash bin blocks electr	rical switch clear floor space
Proposed Solution:	Move stored items at	control or mechanism
As-Built Meas	: 1 Quantity:	JOB Cost Estimate: \$0.00 BSR: 1 Necessary
X Coordinate:	N/A	Y Coordinate: N/A Z Coordinate: N/A
Implementati	on: Priority 3	Phase Date Status Closed
Notes: Clo	sed 12-07-2021 ADA Co	ompliance Team. Photo in closed barrier folder.
Field Date:	11/14/2017 Repo	ort Date: 1/9/2019 Barrier #: 19G
Facility:	Humboldt County DHF	HS - 605 K St, Eureka
Location:	Men's Restroom	
Official Respo	nsible: Karen Clower	r, ADA Coordinator
Consent Decr	ee: No	Paragraph: M.51 Dwg: 1 of 1
Barrier Area:	Restrooms	Remediation: Required
Barrier Type:	Dispensers - Control P	roint
Barrier Description:	Dispenser control poir	nt or operating mechanism not max. 40" AFF
Code Referen	ces: CBC 11B-603.5	
As Built Description:	Hand sanitizer dispens	ser 45-3/4" high
Proposed Solution:	Replace or remount di	ispenser
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$125.00 BSR: 2 Recommended
X Coordinate:	N/A	Y Coordinate: N/A Z Coordinate: N/A
Implementati	on: Priority 3	Phase Date Status Open
Notes:		



Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 19H
Facility: Humboldt County DHHS - 605 K St, Eureka
Location: Men's Restroom
Official Responsible: Karen Clower, ADA Coordinator
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Restrooms Remediation: Required
Barrier Type: Dispensers - Protruding Object
Barrier Dispenser creates protruding object in path of travel Description:
Code References: CBC 11B-307.2 and 2010 ADAS 307.2
As Built Hand sanitizer dispenser protrudes 4-1/2" at 45-1/2" high Description:
Proposed Relocate/remount dispenser or provide detectable warning Solution:
As-Built Meas: 0 Quantity: EACH Cost Estimate: \$0.00 BSR: 2 Recommended
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 3 Phase Date Status Closed
Notes: Closed 12-07-2021 ADA Compliance Team. Photo in closed barrier folder.
Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 191
Facility: Humboldt County DHHS - 605 K St, Eureka
Location: Men's Restroom
Official Responsible: Property Owner
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Restrooms Remediation: Required
Barrier Type: Lavatory - Knee Clearance
Barrier Lavatory bottom apron/edge not max 29" reducing to 27" at 8" back from edge Description:
Code References: CBC 11B-606.2 and 2010 ADAS 606.2
As Built 26" high knee clearance Description:
Proposed Provide min. one accessible lavatory Solution:
As-Built Meas: 1 Quantity: JOB Cost Estimate: \$450.00 BSR: 1 Necessary
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 3 Phase Date Status Open
Notes:



Field Date:	11/14/2017 Repo	rt Date: 1/9/2019	Barrier #: 19J		1
Facility:	Humboldt County DHHS - 605 K St, Eureka				
Location:	Men's Restroom				
Official Respo	nsible: Property Own	ner		F	,
Consent Decr	ee: No	Paragraph: M.51	Dwg: 1 of	1	
Barrier Area:	Restrooms	Remediati	on: Required		
Barrier Type:	Lavatory - Drain Pipes				
Barrier Description:	Hot water and drainpi	pes accessible under lavato	ory not insulated	d or covered	
Code Referen	ces: CBC 11B-606.5 ar	d 2010 ADAS 606.5			
As Built Description:	Not fully insulated				
Proposed Solution:	Insulate drainpipes an	d hot water pipes			
As-Built Meas	: 1 Quantity:	EACH Cost Estimate:	\$220.00	BSR: 2 Recommended	
X Coordinate:	N/A	Y Coordinate: N/A	Z C	oordinate: N/A	
Implementati	on: Priority 3	Phase	Date	Status Open	
Notes:					
Field Date:	11/14/2017 Repo	rt Date: 1/9/2019	Barrier #: 19K		1
Facility:	Humboldt County DH	IS - 605 K St, Eureka			
Location:	Men's Restroom				1
Official Respo	nsible: Karen Clower	, ADA Coordinator			
Consent Decre	ee: No	Paragraph: M.51	Dwg: 1 of	1	
Barrier Area:	Restrooms	Remediati	on: Required		
Barrier Type:	Dispensers - Control P	oint			
Barrier Description:	Dispenser control poir	it or operating mechanism	not max. 40" A	FF	
Code Referen	ces: CBC 11B-603.5				
As Built Description:	Paper towel dispenser	44-3/8" high			
Proposed Solution:	Replace or remount di	spenser			
As-Built Meas	: 1 Quantity:	EACH Cost Estimate:	\$125.00	BSR: 2 Recommended	
X Coordinate:	N/A	Y Coordinate: N/A	ZC	oordinate: N/A	
Implementati	on: Priority 3	Phase	Date	Status Open	
Notes:					



ield Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 19L	
acility: Humboldt County DHHS - 605 K St, Eureka	
ocation: Men's Restroom	11
Official Responsible: Karen Clower, ADA Coordinator	
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1	A CONTRACTOR OF THE PARTY OF TH
Barrier Area: Restrooms Remediation: Required	Maria Sala
Barrier Type: Dispensers - Protruding Object	
Dispenser creates protruding object in path of travel Description:	
Code References: CBC 11B-307.2 and 2010 ADAS 307.2	
Paper towel dispenser protrudes 7" at 44-3/8" high Description:	
Relocate/remount dispenser or provide detectable warning colution:	
As-Built Meas: 1 Quantity: EACH Cost Estimate: \$125.00 BSR: 2 Recommended	
Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A	
mplementation: Priority 3 Phase Date Status Open	
Notes:	
ield Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 19M	
ield Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 19M Humboldt County DHHS - 605 K St, Eureka	
acility: Humboldt County DHHS - 605 K St, Eureka	
acility: Humboldt County DHHS - 605 K St, Eureka ocation: Men's Restroom	
acility: Humboldt County DHHS - 605 K St, Eureka ocation: Men's Restroom Official Responsible: Property Owner Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: Required	
Property Owner Consent Decree: No Paragraph: M.51 Dwg: 1 of 1	
acility: Humboldt County DHHS - 605 K St, Eureka ocation: Men's Restroom Official Responsible: Property Owner Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: Required	
Humboldt County DHHS - 605 K St, Eureka Ocation: Men's Restroom Official Responsible: Property Owner Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: Required Barrier Type: Urinal - Alcove Barrier Urinal alcove not min. 36" wide	
Facility: Humboldt County DHHS - 605 K St, Eureka Ocation: Men's Restroom Official Responsible: Property Owner Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Barrier Type: Urinal - Alcove Description: Virinal alcove not min. 36" wide	
Facility: Humboldt County DHHS - 605 K St, Eureka Occation: Men's Restroom Official Responsible: Property Owner Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: Required Barrier Type: Urinal - Alcove Barrier Occation: Urinal alcove not min. 36" wide Code References: CBC 11B-305.7.1 and 2010 ADAS 305.7.1 As Built 30-3/4" wide and 36-1/2" deep to privacy wall adjacent to storage cabinet	
Humboldt County DHHS - 605 K St, Eureka ocation: Men's Restroom Official Responsible: Property Owner Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Barrier Type: Urinal - Alcove Barrier Urinal alcove not min. 36" wide Code References: CBC 11B-305.7.1 and 2010 ADAS 305.7.1 As Built Description: Broposed Remove cabinet and move privacy wall adjacent to storage cabinet Code References: Remove cabinet and move privacy wall to provide min. 36" wide alcove at urinal Code References: Remove cabinet and move privacy wall to provide min. 36" wide alcove at urinal Code Remove Cabinet and move privacy wall to provide min. 36" wide alcove at urinal Code Remove Cabinet and move privacy wall to provide min. 36" wide alcove at urinal Code Remove Cabinet and move privacy wall to provide min. 36" wide alcove at urinal Code Remove Cabinet and move privacy wall to provide min. 36" wide alcove at urinal Code Remove Cabinet and move privacy wall to provide min. 36" wide alcove at urinal Code Remove Cabinet and move privacy wall to provide min. 36" wide alcove at urinal Code Remove Cabinet and move privacy wall to provide min. 36" wide alcove at urinal Code Remove Cabinet and move privacy wall to provide min. 36" wide alcove at urinal Code Remove Cabinet and move privacy wall to provide min. 36" wide alcove at urinal Code Remove Cabinet and move privacy wall to provide min. 36" wide alcove at urinal	
Humboldt County DHHS - 605 K St, Eureka Ocation: Men's Restroom Official Responsible: Property Owner Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Barrier Type: Urinal - Alcove Urinal alcove not min. 36" wide Code References: CBC 11B-305.7.1 and 2010 ADAS 305.7.1 As Built Description: Proposed Remove cabinet and move privacy wall adjacent to storage cabinet Remove cabinet and move privacy wall to provide min. 36" wide alcove at urinal	
Humboldt County DHHS - 605 K St, Eureka ocation: Men's Restroom Official Responsible: Property Owner Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Sarrier Area: Restrooms Barrier Type: Urinal - Alcove Sarrier Urinal alcove not min. 36" wide Oescription: Code References: CBC 11B-305.7.1 and 2010 ADAS 305.7.1 As Built Description: Proposed Remove cabinet and move privacy wall adjacent to storage cabinet Oroposed Colution: Remove cabinet and move privacy wall to provide min. 36" wide alcove at urinal ObsBuilt Meas: 12 Quantity: SF Cost Estimate: \$6,900.00 BSR: 2 Recommended	



Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 19N	-
Facility: Humboldt County DHHS - 605 K St, Eureka	
Location: Men's Restroom	
Official Responsible: Property Owner	
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1	
Barrier Area: Restrooms Remediation: Required	The second
Barrier Type: Urinal - Rim	
Barrier Urinal rim is not min. 17" from floor or lacks elongated rim projecting min. 13-1/2" from wall Description:	
Code References: CBC 11B-605.2 and 2010 ADAS 605.2	
As Built 17-1/4" high and 12-1/2" elongated rim Description:	
Proposed Provide min. one accessible urinal Solution:	
As-Built Meas: 1 Quantity: JOB Cost Estimate: \$800.00 BSR: 2 Recommended	
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A	
Implementation: Priority 3 Phase Date Status Closed	
Notes: Per 213.3.3 of the ADA 2010 standards, urinals are only required to be accessible if there are two or more unprovided in a toilet room. Urinals [§213.3.3, §605] – ADA Compliance Team	inals
Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 190	111
Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 190 Humboldt County DHHS - 605 K St, Eureka	
1202.7.222	
Facility: Humboldt County DHHS - 605 K St, Eureka	
Facility: Humboldt County DHHS - 605 K St, Eureka Location: Men's Restroom	
Facility: Humboldt County DHHS - 605 K St, Eureka Location: Men's Restroom Official Responsible: Property Owner	A HATTER OF THE SECOND
Facility: Humboldt County DHHS - 605 K St, Eureka Location: Men's Restroom Official Responsible: Property Owner Consent Decree: No Paragraph: M.51 Dwg: 1 of 1	
Facility: Humboldt County DHHS - 605 K St, Eureka Location: Men's Restroom Official Responsible: Property Owner Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: Required	
Facility: Humboldt County DHHS - 605 K St, Eureka Location: Men's Restroom Official Responsible: Property Owner Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: Required Barrier Type: Self-closing Door Stall door or restroom entry door not equipped with a closing device	
Facility: Humboldt County DHHS - 605 K St, Eureka Location: Men's Restroom Official Responsible: Property Owner Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: Required Barrier Type: Self-closing Door Stall door or restroom entry door not equipped with a closing device Description:	
Facility: Humboldt County DHHS - 605 K St, Eureka Location: Men's Restroom Official Responsible: Property Owner Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: Required Barrier Type: Self-closing Door Barrier Description: Code References: CBC 11B-604.8.1.2 and 2010 ADAS 603.8.1.2 As Built Stall door not self-closing	
Facility: Humboldt County DHHS - 605 K St, Eureka Location: Men's Restroom Official Responsible: Property Owner Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: Required Barrier Type: Self-closing Door Barrier Stall door or restroom entry door not equipped with a closing device Description: Code References: CBC 11B-604.8.1.2 and 2010 ADAS 603.8.1.2 As Built Stall door not self-closing Description: Proposed Replace compartment hinge with adjustable mechanism	
Facility: Humboldt County DHHS - 605 K St, Eureka Location: Men's Restroom Official Responsible: Property Owner Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: Required Barrier Type: Self-closing Door Barrier Description: Code References: CBC 11B-604.8.1.2 and 2010 ADAS 603.8.1.2 As Built Description: Proposed Solution: Replace compartment hinge with adjustable mechanism	
Facility: Humboldt County DHHS - 605 K St, Eureka Location: Men's Restroom Official Responsible: Property Owner Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: Required Barrier Type: Self-closing Door Barrier Description: Code References: CBC 11B-604.8.1.2 and 2010 ADAS 603.8.1.2 As Built Description: Proposed Replace compartment hinge with adjustable mechanism Solution: As-Built Meas: 1 Quantity: JOB Cost Estimate: \$240.00 BSR: 2 Recommended	



ield Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 19P	11
acility: Humboldt County DHHS - 605 K St, Eureka	
ocation: Men's Restroom	H
Official Responsible: Property Owner	H
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1	H
Barrier Area: Restrooms Remediation: Required	
Barrier Type: Stall Door Hardware - Outer U-pull	
Outside of compartment door lacks a loop or U-pull below latch Description:	
Code References: CBC 11B-604.8.1.2 and 2010 ADAS 603.8.1.2	
No u-pull provided on either side of door Description:	
Proposed Provide compliant hardware colution:	
As-Built Meas: 1 Quantity: EACH Cost Estimate: \$300.00 BSR: 1 Necessary	
Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A	
mplementation: Priority 3 Phase Date Status Open	
Notes:	
ield Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 19Q	
rield Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 19Q Facility: Humboldt County DHHS - 605 K St, Eureka	
in the same of the	
Facility: Humboldt County DHHS - 605 K St, Eureka	
acility: Humboldt County DHHS - 605 K St, Eureka ocation: Men's Restroom	
acility: Humboldt County DHHS - 605 K St, Eureka ocation: Men's Restroom Official Responsible: Property Owner	
Property Owner Consent Decree: No Paragraph: M.51 Dwg: 1 of 1	
acility: Humboldt County DHHS - 605 K St, Eureka ocation: Men's Restroom Official Responsible: Property Owner Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Required	
Humboldt County DHHS - 605 K St, Eureka Ocation: Men's Restroom Official Responsible: Property Owner Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: Required Barrier Type: Stall Door Hardware - Inner U-pull Barrier Inside of compartment door lacks a loop or U-pull below latch	
Humboldt County DHHS - 605 K St, Eureka Ocation: Men's Restroom Official Responsible: Property Owner Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: Required Barrier Type: Stall Door Hardware - Inner U-pull Barrier Oescription: Inside of compartment door lacks a loop or U-pull below latch	
Facility: Humboldt County DHHS - 605 K St, Eureka Occation: Men's Restroom Official Responsible: Property Owner Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: Required Barrier Type: Stall Door Hardware - Inner U-pull Barrier Unside of compartment door lacks a loop or U-pull below latch Code References: CBC 11B-604.8.1.2 and 2010 ADAS 603.8.1.2 No u-pull provided on inside of door	
Humboldt County DHHS - 605 K St, Eureka Ocation: Men's Restroom Official Responsible: Property Owner Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: Required Barrier Type: Stall Door Hardware - Inner U-pull Barrier Oescription: Code References: CBC 11B-604.8.1.2 and 2010 ADAS 603.8.1.2 No u-pull provided on inside of door Proposed Provide compliant hardware	
Accility: Humboldt County DHHS - 605 K St, Eureka Docation: Men's Restroom Official Responsible: Property Owner Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Barrier Type: Stall Door Hardware - Inner U-pull Barrier Poescription: Inside of compartment door lacks a loop or U-pull below latch Code References: CBC 11B-604.8.1.2 and 2010 ADAS 603.8.1.2 No u-pull provided on inside of door Proposed Provide compliant hardware	
Acacility: Humboldt County DHHS - 605 K St, Eureka Ocation: Men's Restroom Official Responsible: Property Owner Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Starrier Area: Restrooms Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Starrier Type: Stall Door Hardware - Inner U-pull Starrier Code References: CBC 11B-604.8.1.2 and 2010 ADAS 603.8.1.2 As Built Description: No u-pull provided on inside of door Coposed Colution: Provide compliant hardware Colution: As-Built Meas: 1 Quantity: EACH Cost Estimate: \$300.00 BSR: 1 Necessary	



Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 19R
Facility: Humboldt County DHHS - 605 K St, Eureka
Location: Men's Restroom
Official Responsible: Property Owner
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Restrooms Remediation: Required
Barrier Type: Clothing Hooks - Height
Barrier Clothing hooks not max. 48" high AFF Description:
Code References: CBC 11B-603.4, 11B-308.2.1 & 2010 ADA 603.4
As Built 59-3/4" high Description:
Proposed Provide additional hook in compliant location Solution:
As-Built Meas: 1 Quantity: EACH Cost Estimate: \$125.00 BSR: 2 Recommended
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 3 Phase Date Status Open
Notes:
Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 19S
Facility: Humboldt County DHHS - 605 K St, Eureka
Location: Men's Restroom
Official Responsible: Property Owner
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Restrooms Remediation: Required
Barrier Type: WC - Rear Grab Bar Location
Barrier Rear grab bar not centered 12" from wall and 24" on the other side of WC Description:
Code References: CBC 11B-604.5.2 and 2010 ADAS 604.5.2
As Built 17-1/2" OC Description:
Proposed Provide compliant grab bars with required reinforcement Solution:
As-Built Meas: 1 Quantity: JOB Cost Estimate: \$1,450.00 BSR: 3 Hindrance
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 3 Phase Date Status Open



Field Date:	11/14/2017 Report Date: 1/9/2019 Barrier #: 19T				
Facility:	Humboldt County DHHS - 605 K St, Eureka				
Location:	Men's Restroom				
Official Respo	nsible: Property Owner				
Consent Decr	ee: No Paragraph: M.51 Dwg: 1 of 1				
Barrier Area:	Restrooms Remediation: Required				
Barrier Type:	WC - Side Grab Bar Extension				
Barrier Description:	Side grab bar does not extend min. 54" from rear wall or 24" from front rim				
Code Referen	ces: CBC 11B-604.5.1 and 2010 ADAS 604.5.1				
As Built Description:	53" from rear wall				
Proposed Solution:	Provide compliant grab bars with required reinforcement				
As-Built Meas	: 1 Quantity: JOB Cost Estimate: \$1,450.00 BSR: 3 Hindrance				
X Coordinate:	N/A Y Coordinate: N/A Z Coordinate: N/A				
Implementati	on: Priority 3 Phase Date Status Open				
Notes:					
Field Date:	11/14/2017 Report Date: 1/9/2019 Barrier #: 19U				
Facility:	Humboldt County DHHS - 605 K St, Eureka				
Location:	Men's Restroom				
Official Respo	nsible: Karen Clower, ADA Coordinator				
Consent Decre	ee: No Paragraph: M.51 Dwg: 1 of 1				
Barrier Area:	Restrooms Remediation: Required				
Barrier Type:	Toilet Paper Dispenser - Above Grab Bar				
Barrier Description:	Toilet tissue dispenser mounted above the grab bar within 12" of bar				
Code Referen	ces: CBC 11B-604.5 & 609.3 and 2010 ADAS 604.5 & 609.3				
As Built Description:	7-1/2" above grab bar				
Proposed Solution:	Reposition or replace toilet paper dispenser				
As-Built Meas	: 1 Quantity: EACH Cost Estimate: \$225.00 BSR: 2 Recommended				
X Coordinate:	N/A Y Coordinate: N/A Z Coordinate: N/A				
Implementati	on: Priority 3 Phase Date Status Open				
Notes:					



Field Date:	11/14/2017 Repo	rt Date: 1/9/2019 Ba	rrier #: 19V	
Facility:	Humboldt County DHF	IS - 605 K St, Eureka		
Location:	Men's Restroom			
Official Respo	nsible: Karen Clower	, ADA Coordinator	-	5
Consent Decre	ee: No	Paragraph: M.51	Dwg: 1 of 1	
Barrier Area:	Restrooms	Remediation	n: Required	· 中国中国中国中国中国中国中国中国中国中国中国中国中国中国中国中国中国中国中国
Barrier Type:	Toilet Paper Dispenser	- Centerline		
Barrier Description:	Centerline of toilet tiss	sue dispenser not within 7" to	o 9" toilet seat front edg	ge
Code Referen	ces: CBC 11B-604.7 an	d 2010 ADAS 604.7		
As Built Description:	3" from rim			
Proposed Solution:	Reposition or replace t	oilet paper dispenser		
As-Built Meas	: 0 Quantity:	EACH Cost Estimate: \$0	.00 BSR: 3 H	indrance
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordinate:	N/A
Implementati	on: Priority 3	Phase	Date	Status Open
Notes:				
Field Date:	11/14/2017 Repo	rt Date: 1/9/2019 Ba	rrier #: 19W	
Facility:	Humboldt County DHF	IS - 605 K St, Eureka		
Location:	Men's Restroom			
Official Respo	nsible: Karen Clower	, ADA Coordinator		
Consent Decre	ee: No	Paragraph: M.51	Dwg: 1 of 1	
Barrier Area:	Restrooms	Remediation	n: Required	
Barrier Type:	Toilet Paper Dispenser	- Height		
Barrier Description:	Toilet tissue dispenser	outlet not mounted no lowe	er than 19" from floor	
Code Referen	ces: CBC 11B-604.7 (2	010 ADAS 604.7 less stringen	nt)	
As Built Description:	40-1/4" high and abov	e grab bar		
Proposed Solution:	Reposition or replace t	oilet paper dispenser		
As-Built Meas	: 0 Quantity:	EACH Cost Estimate: \$0	.00 BSR: 3 H	indrance
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordinate:	N/A
Implementati	on: Priority 3	Phase	Date	Status Open
Notes:				



Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 19X								
Facility: Humboldt County DHHS - 605 K St, Eureka								
Location: Men's Restroom								
Official Responsible: Property Owner								
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1								
Barrier Area: Restrooms Remediation: Required								
Barrier Type: WC - Seat Height								
Barrier Water closet + seat not between 17" to 19" high Description:								
Code References: CBC 11B-604.4 and 2010 ADAS 604.4								
As Built 16-3/4" high Description:								
Proposed Solution: Provide min. one accessible water closet								
As-Built Meas: 1 Quantity: JOB Cost Estimate: \$850.00 BSR: 2 Recommended								
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A								
Implementation: Priority 3 Phase Date Status Open								
Notes:								
Field Date: 11/14/2017 Report Date: 1/9/2019 Barrier #: 20A								
Facility: Humboldt County DHHS - 605 K St, Eureka								
Location: Staff Entrance from Parking								
Official Responsible: Property Owner								
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1								
Barrier Area: Signage Remediation: Required								
Barrier Type: Tactile Exit Sign - Exit								
Barrier Description: Ground floor doors that exit to exterior not provided with signs stating "EXIT"								
Code References: CBC 11B-216.4.1 & 11B-703 and 2010 ADAS 216.4.1								
As Built Description: No tactile sign provided where required								
Proposed Solution: Provide compliant sign at exit side of door								
As-Built Meas: 1 Quantity: EACH Cost Estimate: \$250.00 BSR: 1 Necessary								
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A								
Implementation: Priority 4 Phase Date Status Closed								
Notes: Closed 12-07-2021 ADA Compliance Team. Photo in closed barrier folder.								



	11/14/2017 Report Date: 1/9/2019 Barrier #: 20B						
Facility:	Humboldt County DHHS - 605 K St, Eureka						
Location:	cation: Staff Entrance from Parking						
Official Respo	nsible: Property Owner						
Consent Decre	ee: No Paragraph: M.51 Dwg: 1 of 1						
Barrier Area:	Doors or Gates Remediation: Required						
Barrier Type:	Door Closer - Exterior Adjustment						
Barrier Description:	Door opening force exceeds 5 lbf						
Code Referen	Ces: CBC 11B-404.2.9						
As Built Description:	12 lbf						
Proposed Solution:	Replace or adjust existing closer						
As-Built Meas	Quantity: EACH Cost Estimate: \$450.00 BSR: 1 Necessary						
X Coordinate:	N/A Y Coordinate: N/A Z Coordinate: N/A						
Implementation	on: Priority 2 Phase Date Status Open						
Notes:							
Field Date:	Let / 1 / 2 / 2 Parant Pater 1 / 2 / 2 / 2 Parain # 2 / 2 / 2						
Field Date:	11/14/2017 Report Date: 1/9/2019 Barrier #: 20C						
Facility:	Humboldt County DHHS - 605 K St, Eureka						
Facility:							
Facility:	Humboldt County DHHS - 605 K St, Eureka Staff Entrance from Parking						
Facility: Location:	Humboldt County DHHS - 605 K St, Eureka Staff Entrance from Parking nsible: Property Owner						
Facility: Location: Official Respo Consent Decre Barrier Area:	Humboldt County DHHS - 605 K St, Eureka Staff Entrance from Parking nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Remediation: Required						
Facility: Location: Official Respo Consent Decre Barrier Area:	Humboldt County DHHS - 605 K St, Eureka Staff Entrance from Parking nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1						
Facility: Location: Official Respo Consent Decre Barrier Area:	Humboldt County DHHS - 605 K St, Eureka Staff Entrance from Parking nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Remediation: Required						
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description:	Humboldt County DHHS - 605 K St, Eureka Staff Entrance from Parking nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Remediation: Required Door Closer - Exterior Sweep						
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description:	Humboldt County DHHS - 605 K St, Eureka Staff Entrance from Parking nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Remediation: Required Door Closer - Exterior Sweep Door closer lacks min. 5 second sweep period/back check						
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built	Humboldt County DHHS - 605 K St, Eureka Staff Entrance from Parking nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Remediation: Required Door Closer - Exterior Sweep Door closer lacks min. 5 second sweep period/back check Ces: CBC 11B-404.2.8.1 and 2010 ADAS 404.2.8.1						
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed	Humboldt County DHHS - 605 K St, Eureka Staff Entrance from Parking nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Door Closer - Exterior Sweep Door closer lacks min. 5 second sweep period/back check ces: CBC 11B-404.2.8.1 and 2010 ADAS 404.2.8.1 2 second sweep Replace or adjust existing closer						
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed Solution:	Humboldt County DHHS - 605 K St, Eureka Staff Entrance from Parking nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Door Closer - Exterior Sweep Door closer lacks min. 5 second sweep period/back check ces: CBC 11B-404.2.8.1 and 2010 ADAS 404.2.8.1 2 second sweep Replace or adjust existing closer EQ Quantity: EACH Cost Estimate: \$0.00 BSR: 2 Recommended						
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed Solution: As-Built Meas	Humboldt County DHHS - 605 K St, Eureka Staff Entrance from Parking Insible: Property Owner Insible:						



Field Date:	11/14/2017 Repor	rt Date: 1/9/2019 Barrier #: 20D						
Facility:	Humboldt County DHHS - 605 K St, Eureka							
Location:	ion: Staff Entrance from Parking							
Official Responsible: Property Owner								
Consent Decre	ee: No	Paragraph: M.51 Dwg: 1 of 1						
Barrier Area:	Doors or Gates	Remediation: Required						
Barrier Type:	Vision Lights - Existing							
Barrier Description:	Doors, gates, and side	lights adjacent to opening not max. 43" abo	ve floor/ground					
Code Referen	ces: CBC 11B-404.2.11	. and 2010 ADAS 404.2.11						
As Built Description:	55-3/4" high							
Proposed Solution:	Replace door or vision	panel in door						
As-Built Meas	Quantity:	EACH Cost Estimate: \$2,250.00	BSR: 3 Hindrance					
X Coordinate:	N/A	Y Coordinate: N/A Z Coo	ordinate: N/A					
Implementation	on: Priority 2	Phase Date	Status Open					
Notes:								
Field Date:	11/14/2017 Repor	rt Date: 1/9/2019 Barrier #: 20E						
Field Date: Facility:	11/14/2017 Repor	, , , , , , , , , , , , , , , , , , , ,						
		IS - 605 K St, Eureka						
Facility:	Humboldt County DHH Staff Entrance from Pa	dS - 605 K St, Eureka orking						
Facility: Location:	Humboldt County DHH Staff Entrance from Pa nsible: Property Owr	dS - 605 K St, Eureka orking						
Facility: Location: Official Respo Consent Decre	Humboldt County DHH Staff Entrance from Pa nsible: Property Owr	dS - 605 K St, Eureka orking ner	=					
Facility: Location: Official Respo Consent Decre Barrier Area:	Humboldt County DHH Staff Entrance from Pa nsible: Property Owr ee: No	rking Paragraph: M.51 Dwg: 1 of 1 Remediation: Required						
Facility: Location: Official Respo Consent Decre Barrier Area:	Humboldt County DHH Staff Entrance from Pa nsible: Property Owr ee: No Doors or Gates Maneuvering CI - Ext F	rking Paragraph: M.51 Dwg: 1 of 1 Remediation: Required						
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description:	Humboldt County DHH Staff Entrance from Pa nsible: Property Owr ee: No Doors or Gates Maneuvering CI - Ext F Door/Gate at pull side	AS - 605 K St, Eureka orking ner Paragraph: M.51 Dwg: 1 of 1 Remediation: Required oront App/Pull 24"						
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description:	Humboldt County DHH Staff Entrance from Pa nsible: Property Owr ee: No Doors or Gates Maneuvering CI - Ext F Door/Gate at pull side ces: CBC Figure 11B-40	AS - 605 K St, Eureka Irking Per Paragraph: M.51 Dwg: 1 of 1 Remediation: Required Front App/Pull 24" of exterior door lacks min. 24" beyond latch						
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built	Humboldt County DHH Staff Entrance from Pa nsible: Property Owr ee: No Doors or Gates Maneuvering CI - Ext F Door/Gate at pull side ces: CBC Figure 11B-40 7" maneuvering cleara	AS - 605 K St, Eureka Irking ner Paragraph: M.51 Dwg: 1 of 1 Remediation: Required Front App/Pull 24" of exterior door lacks min. 24" beyond latch 04.2.4.1 and 2010 ADAS 404.2.4.1	n side of door					
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed	Humboldt County DHH Staff Entrance from Pa nsible: Property Owr ee: No Doors or Gates Maneuvering CI - Ext F Door/Gate at pull side ces: CBC Figure 11B-40 7" maneuvering cleara Install automatic door	AS - 605 K St, Eureka Arking Ther Paragraph: M.51 Dwg: 1 of 1 Remediation: Required Front App/Pull 24" of exterior door lacks min. 24" beyond latch D4.2.4.1 and 2010 ADAS 404.2.4.1 Ince at pull side of door opening device at door serving accessible paragraphs.	n side of door					
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed Solution:	Humboldt County DHH Staff Entrance from Pansible: Property Ownee: No Doors or Gates Maneuvering CI - Ext F Door/Gate at pull side ces: CBC Figure 11B-40 7" maneuvering cleara Install automatic door : 1 Quantity:	AS - 605 K St, Eureka Irking Ther Paragraph: M.51 Dwg: 1 of 1 Remediation: Required Front App/Pull 24" of exterior door lacks min. 24" beyond latch D4.2.4.1 and 2010 ADAS 404.2.4.1 Ince at pull side of door Opening device at door serving accessible paragraphs.	arking used by staff					
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed Solution: As-Built Meas	Humboldt County DHH Staff Entrance from Pansible: Property Ownee: No Doors or Gates Maneuvering CI - Ext F Door/Gate at pull side ces: CBC Figure 11B-40 7" maneuvering cleara Install automatic door : 1 Quantity: N/A	AS - 605 K St, Eureka Irking Ther Paragraph: M.51 Dwg: 1 of 1 Remediation: Required Front App/Pull 24" of exterior door lacks min. 24" beyond latch D4.2.4.1 and 2010 ADAS 404.2.4.1 Ince at pull side of door Opening device at door serving accessible paragraphs.	arking used by staff BSR: 1 Necessary					



Field Date:	11/14/2017 Report Date: 1/9/2019 Barrier #: 20F						
Facility:	Humboldt County DHHS - 605 K St, Eureka						
Location:	n: Staff Entrance from Parking						
Official Responsible: Property Owner							
Consent Decre	e: No Paragraph: M.51 Dwg: 1 of 1						
Barrier Area:	Doors or Gates Remediation: Required						
Barrier Type:	Threshold (replacement)						
Barrier Description:	Door/Gate threshold height exceeds 1/2" with a bevel						
Code Reference	ces: CBC 11B-404.2.5 and 2010 ADAS 404.2.5						
As Built Description:	3/4" high threshold						
Proposed Solution:	Provide new door threshold						
As-Built Meas:	1 Quantity: EACH Cost Estimate: \$275.00 BSR: 1 Necessary						
X Coordinate:	N/A Y Coordinate: N/A Z Coordinate: N/A						
Implementation	on: Priority 2 Phase Date Status Open						
Notes:							
Field Date:	11/14/2017 Report Date: 1/9/2019 Barrier #: 20G						
,	11/14/2017 Report Date: 1/9/2019 Barrier #: 20G Humboldt County DHHS - 605 K St, Eureka						
Facility:	Humboldt County DHHS - 605 K St, Eureka						
Facility:	Humboldt County DHHS - 605 K St, Eureka Staff Entrance from Parking						
Facility: Location:	Humboldt County DHHS - 605 K St, Eureka Staff Entrance from Parking nsible: Property Owner						
Facility: Location: Official Respor Consent Decre Barrier Area:	Humboldt County DHHS - 605 K St, Eureka Staff Entrance from Parking nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Remediation: Required						
Facility: Location: Official Respor Consent Decre Barrier Area:	Humboldt County DHHS - 605 K St, Eureka Staff Entrance from Parking nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1						
Facility: Location: Official Respor Consent Decre Barrier Area:	Humboldt County DHHS - 605 K St, Eureka Staff Entrance from Parking nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Remediation: Required						
Facility: Location: Official Respondence Consent Decree Barrier Area: Barrier Type: Barrier Description:	Humboldt County DHHS - 605 K St, Eureka Staff Entrance from Parking nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Remediation: Required Door/Gate Landing - Slope 2.1% to 3.0%						
Facility: Location: Official Respondence Consent Decree Barrier Area: Barrier Type: Barrier Description:	Humboldt County DHHS - 605 K St, Eureka Staff Entrance from Parking nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Remediation: Required Door/Gate Landing - Slope 2.1% to 3.0% Door/Gate landing is not level on both sides of door (2.1% to 3.0%)						
Facility: Location: Official Respondence Consent Decree Barrier Area: Barrier Type: Barrier Description: Code Reference As Built	Humboldt County DHHS - 605 K St, Eureka Staff Entrance from Parking nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Remediation: Required Door/Gate Landing - Slope 2.1% to 3.0% Door/Gate landing is not level on both sides of door (2.1% to 3.0%) ees: CBC 11B-404.2.4.4 and 2010 ADAS 404.2.4.4						
Facility: Location: Official Respondence Consent Decree Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed	Humboldt County DHHS - 605 K St, Eureka Staff Entrance from Parking nsible: Property Owner ee: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Door/Gate Landing - Slope 2.1% to 3.0% Door/Gate landing is not level on both sides of door (2.1% to 3.0%) ees: CBC 11B-404.2.4.4 and 2010 ADAS 404.2.4.4 2.4% slope Demolish and reconstruct level landing						
Facility: Location: Official Respondence Consent Decree Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed Solution:	Humboldt County DHHS - 605 K St, Eureka Staff Entrance from Parking nsible: Property Owner nsible: No Paragraph: M.51 Dwg: 1 of 1 Doors or Gates Remediation: Required Door/Gate Landing - Slope 2.1% to 3.0% Door/Gate landing is not level on both sides of door (2.1% to 3.0%) nes: CBC 11B-404.2.4.4 and 2010 ADAS 404.2.4.4 2.4% slope Demolish and reconstruct level landing 20 Quantity: SF Cost Estimate: \$2,500.00 BSR: 3 Hindrance						
Facility: Location: Official Respondence Consent Decree Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed Solution: As-Built Meas:	Humboldt County DHHS - 605 K St, Eureka Staff Entrance from Parking Insible: Property Owner Insible:						



Field Date:	11/14/2017 Report Date: 1/9/2019 Barrier #: 20H						
Facility:	Humboldt Count						
Location:	Staff Entrance fro						
Official Respon	nsible: Karen Cl	ower, ADA Coor	dinator		-		
Consent Decre	ee: No	Paragraph	: M.51	Dwg:	1 of 1	n *	
Barrier Area:	Signage		Remedia	tion: Requir	red		
Barrier Type:	Room ID Sign - N	o Tactile Informa	ntion				
Barrier Room ID sign provided for sighted people lacks tactile info for the visually impaired Description:							
Code Reference	ces: CBC 11B-216	5.2 and 2010 AD	AS 216.2				
As Built Description:	No tactile inform	ation provided w	here visual si	gn exists			
Proposed Solution:	Provide room ID	sign with tactile	information a	t wall at latch	n side of doo	r	
As-Built Meas:	Quar	ntity: EACH Co	ost Estimate:	\$250.00	BSR:	1 Necessary	
X Coordinate:	N/A	Y Coordina	nte: N/A		Z Coordina	te: N/A	
Implementation	on: Priority 4	Phase		Date		Status Open	
Notes:							

