



**Existing bathroom showing cracked tile flooring. Failing lights and ceiling fan not shown.**



**Existing hallway showing carpet wear and staining.**



**Existing floor in former dispatch office. Flooring failing at most joints.**



**Existing reception area carpet showing wear and staining.**